

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1102Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CUT	458.60	458.60
1	REAR BUMPER LOWER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	REAR BUMPER TOW COVER	MISSING	82.70	82.70
1	REAR BUMPER SIDE COVER RH	TO REPAIR SEE LABOUR	232.00	-
1	REAR TRUNK LOGO PRIUS	NECESSARY	52.90	52.90
1	REAR TRUNK LOGO HYBRID	NECESSARY	52.40	52.40
2	REAR BUMPER SIDE RETAINER LH/RH @\$112.70	SERVICEABLE	225.40	-
10	REAR BUMPER CLIP @\$2.20	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-499.35	-305.30
			1,498.05	915.90
	NETT ITEMS			
1	BOOT LID COMFORT & TEL NUMBER (N)	NECESSARY	60.00	60.00
1	BOOTLID COMFORT APP (N)	NECESSARY	40.00	40.00
1	BUMPER REVERSE SENSOR (N)	CUT	135.70	135.70
	LESS 10% DISCOUNT		-23.57	-23.57
			212.13	212.13
	SPECIAL NETT ITEMS			
1	BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE COVER RH.		600.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK WIRING AND LIGHTING.		60.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			1,320.00	910.00
	GRAND TOTAL		3,080.18	2,088.03

Report Ref No. NS/INC21010519/Vtcn2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,650.00
(TO ITS PRE-ACCIDENT CONDITION)	
(CONFIRMED)	

Report Ref No. NS/INC21010519/Vtcn2



THEVAN THOMAS KARTHIKESAVAN



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**