

Our Job Ref No : 305489642

Date : 09/10/21

ENGINEERING

ComfortDaiGoo Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6548 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHA1007A

06/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2 The repair job shall bill to: NTUC SJF5305M

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$3,700.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature :

Name : Thuan

Date :

15/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA1007A

03/09/21

MAKE REG.22.11.2018

MODEL IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER STAY /RH		\$138.10	\$138.10
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR UNDER CENTRE COVER			\$225.00
1	BOOTLID COVER - more photos to show damaged			\$2,480.40
1	BOOTLID H EMBLEM			\$38.00
1	BOOTLID EMBLEM IONID			\$31.80
1	BOOTLID EMBLEM HYBRID			\$24.30
1	REAR BUMPER TOW COVER			\$98.80
1	REAR SMART KEY SENSOR			\$40.50
2	REAR BUMPER BRACKET LH /RH		\$55.80	\$111.60
				\$4,515.95
	20.00%			\$903.19
	DISCOUNTED TOTAL			\$3,612.76
1	BOOTLID COMFORT APP STICKER			\$40.00
2	BOOTLID COMFORT /TEL NUMBER STICKER		\$30.00	\$60.00
1	BOOTLID ADVERTISEMENT			\$100.00
1	REAR NUMBER PLATE W/HOLDER			\$55.00
1	REAR REVERSE SENSOR			\$180.00
				\$435.00
	Labour Charge			
	Panel Beating			\$850.00
	Spray Painting Charge			\$600.00
	Check wiring and lighting			\$60.00
	Remove/Refix rear w/screen (big & small)			\$120.00
	Tuff Kote			\$90.00
	Remove/Refix reverse sensor			\$60.00
	TOTAL LABOUR			\$1,780.00
	ESTIMATE TOTAL			\$5,827.76

Thuan @ LKK Auto - Com

82235769

6/10/21 1630

45 for repair photo

3 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

This is an initial estimate based on a visual inspection of the above vehicle. The final repair estimate will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE # SHA1007A

NTUC

305489642

DATE : 06/10/21

[illegible]