



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21010525/Kqf3n2	
			Date: 16/11/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 2324S	Veh. Inspected	GX 5996J	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2103050/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	13/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LITEACE (M)	c.c	2184	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	CR425009310	Colour	METALLIC GREY	
Odometer	179705 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165 R13	BRIDGESTONE	9 mm	
L/H Front Tyre	165 R13	BRIDGESTONE	9 mm	
R/H Rear Tyre	165 R13	BRIDGESTONE	9 mm	
L/H Rear Tyre	165 R13	BRIDGESTONE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/10/2021	Inspection Date	13/10/2021	
Survey held at	160 SIN MING DRIVE #02-07			
Repairer	CAR TIMES AUTOLUTION PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	