



**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2021)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLJ7990B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Mtg Cracked	391.80 FL	*351.80 FL
2	1		*FRONT GRILLE CHROME	Cracked	445.00 FL	*421.00 FL
3	1		*FRONT GRILLE EMBLEM	Necessary	33.40 FL	*33.40 FL
4	1		*HEADLAMP LH	Cut	1,850.00 FL	*1,850.00 FL
5	1		*HEADLAMP LOWER BRACKET LH	Repair	38.00 FL	*- FL
6	1		*HEADLAMP UPPER BRACKET LH	Serviceable	29.60 FL	*- FL
7	1		*FRONT BUMPER	Cracked	881.70 FL	*762.70 FL
8	1		*FRONT BUMPER REINFORCEMENT	Repair	351.00 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER LH	Distorted	27.50 FL	*27.50 FL
10	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	27.50 FL	*- FL
11	1		*FRONT BUMPER BRACKET LH	Repair	29.60 FL	*- FL
12	1		*FRONT BUMPER BRACKET RH	Repair	29.60 FL	*- FL
13	1		*FOG LAMP LH	Serviceable	357.00 FL	*- FL
14	1		*FOG LAMP GARNISH LH	Dented	45.00 FL	*45.00 FL
15	1		*LH FRONT FENDER UNDERSHIELD	Serviceable	155.00 FL	*- FL
16	1		*LH FRONT FENDER PROTECTOR	Buckled	195.00 FL	*195.00 FL
17	10		*FRONT BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
18	10		*LH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	35.00 FS	*- FS
19	10		*LH FRONT FENDER PROTECTOR CLIP	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,991.70</b>	<b>3,756.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	977.34	737.28
<b>Total Parts (\$\$)</b>	<b>4,014.36</b>	<b>3,019.12</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,BONNET,LHF FENDER)	New	800.00	350.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,BONNET,LHF FENDER)	New	800.00	450.00
3	TO CHECK WIRING & FOCUS HEADLAMP	New	50.00	20.00
			<b>Gross Labour Cost (\$\$)</b>	<b>820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >