



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0842/2021/JT
DATE : 12-Oct-21
WIP : 48781

\$14384.72

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LIM GEOK CHOO (LIN YUZHU)
ADDRESS : 127 TAMPINES STREET 11
#08-440
SINGAPORE 521127
TELEPHONE : HP +65 82289550
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210036748
VEHICLE NO : **SMR 8181 J**
MODEL CODE : A6 DESIGN 2.0 TFSI S
MODEL YEAR : 12/4/2021
ENGINE NO : DKY 015270
CHASSIS NO : WAUZZZF27MN051947
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Oct-21
PLACE OF ACCIDENT : 139 TAMPINES ST 11
OPEN SURFACES CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8181 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000 ✓
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,500.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,972.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8181 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FORNT BUMPER <i>Behnd</i>	1	\$ 2,832.00	✓ 2265.60	
2	FRONT BUMPER FIXING PARTS <i>neu</i>	1	\$ 650.00	✓	
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>neu</i>	1	\$ 222.00	✓	
4	FRONT BUMPER APAPTER - RH <i>Damaged</i>	1	\$ 39.00	✓ 31.20	
5	FRONT BUMPER MOUNTING BRACKET - RH <i>Not nec</i>	1	\$ 111.00	✗	
6	FRONT BUMPER LOWER GRILLE <i>neu</i>	1	\$ 153.00	✓	
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>neu</i>	1	\$ 210.00	✓ 167.60	
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>cut</i>	1	\$ 434.00	✓ 346.80	
9	FRONT BUMPER AIR GUIDE - RH <i>cracked</i>	2	\$ 58.00	✓ 22.56	
10	FRONT RADIATOR GRILLE <i>neu</i>	1	\$ 2,217.00	✓	
11	FRONT BUMPER FOAM FILLER PIECE <i>Not nec</i>	1	\$ 226.00	✗	
12	FRONT BUMPER CARRIER <i>Not nec</i>	1	\$ 1,012.00	✗	
13	FRONT BUMPER GUIDE SECTION - RH <i>Dmgd</i>	1	\$ 44.00	✓ 35.12	
14	FRONT BUMPER SUPPORT <i>Not nec</i>	2	\$ 59.00	✗	
15	FRONT BUMPER BRACKET - RH <i>Not nec</i>	1	\$ 54.00	✗	
16	FRONT BUMPER TOP COVER <i>neu</i>	1	\$ 126.00	✓ 100.40	
17	HORN <i>neu</i>	1	\$ 216.00	✓	
18	HORN BRACKET <i>neu</i>	1	\$ 47.00	✓	
19	FRONT PARKING AID SENSOR <i>Not nec</i>	2	TBC	✗	
20	FRONT PARKING AID SENSOR SEAL <i>Not nec</i>	4	\$ 9.00	✗	
SUB TOTAL SPARE PARTS			\$ 8,719.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8181 J

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,468.00	✓	1174.40
22	FRONT FENDER BRACE - RH <i>Beit</i>	1	\$ 118.00	✓	94.40
23	FRONT FENDER BRACKET - RH <i>Not Rec</i>	1	\$ 44.00	X	
24	FRONT FENDER ATTACHEMENT PART <i>new</i>	1	\$ 42.00	+	
25	FRONT WHEEL HOUSING LINER - RH <i>tom</i>	1	\$ 266.00	✓	212.80
26	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 71.00	+	
27	FRONT WHEEL SPOILER - RH <i>new</i>	1	\$ 166.00	+	
28	STONE CHIP GUARD - RH <i>new</i>	1	\$ 51.00	+	
29	HEADLIGHT MOUNTING - RH <i>new</i>	1	\$ 118.00	+	
30	HEADLIGHT - RH <i>cut</i>	1	\$ 8,624.00	✓	6899.20
31	HEADLIGHT LIFT CYLINDER - RH <i>new</i>	1	\$ 198.00	+	
32	HEADLIGHT WASHER HOSE <i>new</i>	1	\$ 182.00	+	
33	FRONT BUMPER WIRING SET <i>Not Rec</i>	1	\$ 577.00	X	
34	FRONT NO PLATE <i>new</i>	S/N	\$ 60.00	+	
35	SUNDRIES <i>Rec.</i>		\$ 300.00	✓	1.76
TOTAL SPARE PARTS		:	\$ 21,004.00		
TOTAL LABOUR CHARGES		:	\$ 5,972.00		
GRAND TOTAL		:	\$ 26,976.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: ~~Adrian~~ Adrian Ly
13/10/21

: Not Authorised, 04 Days
S.L.S.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Hui Zhen

Supplementary Estimate - 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0842/2021/JT
16-Oct-21
CHANG
1 of 1
SMR 8181 J
AUDI A6 DESIGN 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	SIGN ' CAUTION ' STICKER <i>Nec</i>	\$ 14.00	✓ 10.88
GRAND TOTAL		\$ 14.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
AS