

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

TP China

Veh# SMF6920U

Model: HONDA FREED HYBRID
(21/11/2018)

Accident Date : 12/10/2021

GBT1076807

Ceilia

Location : WOODLANDS AVE 3

3P: GBE9589J (CHINA TAIPEG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear bumper <i>Delnd</i>	943.50	✓	
2	10pcs	Rear bumper clips <i>new</i>		40.00	✓
3	2pcs	Rear bumper screw clips <i>new</i>		20.00	✓
4	2pcs	Rear bumper o/s & n/s reflector <i>new</i>	266.00	✓	
5	2pcs	Rear bumper o/s & n/s retainer <i>new</i>	125.00	✓	
6	2pcs	Rear reverse sensor <i>Damaged</i>	465.60	200/SN	
7	1pc	Rear end panel <i>Repair</i>	550.8	✓	
8	1 pc	Rear end panel inner trim <i>Delnd</i>	155.60	✓	
9	2pcs	Rear o/s & n/s tail-lamp <i>N/s cracked, o/s at 1240</i>	1,440.00	✓	
10	2pcs	Rear o/s & n/s tail-lamp clips <i>new</i>		20.00	✓
11	1pc	Rear tail gate <i>Distorted</i>	1,378.00	✓	
12	1pc	Rear tail gate weatherstrip <i>at</i>	285.00	✓	
13	1pc	Rear tail gate 'HONDA' emblem <i>new</i>	95.00	46	
14	1pc	Rear tail gate 'HONDA' emblem wrap <i>new</i>		20.00	✓
15	1pc	Rear tail gate 'FREED' emblem <i>new</i>	85.00	65	
16	1pc	Rear tail gate 'HYBRID' emblem <i>new</i>	76.60	✓	
17	1pc	Rear tail gate inner trim <i>Cracked</i>	310.00	✓	
18	11pcs	Rear tail gate inner trim clips <i>new</i>		44.00	30
19	1 pc	Rear tail gate moulding <i>new</i>	256.50	✓	
20	1pc	Rear tail gate lock (Upper) <i>Jammed</i>	331.00	✓	
21	1pc	Rear tail gate lock (Lower) <i>new</i>	130.00	✓	
22	1 pc	Tailgate handle <i>Delnd</i>	66.4	✓	
23	2 pcs	Rear tail gate o/s & n/s reflector <i>at</i>	940.00	✓	
24	1 pc	Rear windscreen moulding <i>new</i>	210.00	✓	
25	1 pc	Rear windscreen sealant		60.00	✓
26	2pcs	Rear o/s & n/s fender inner trim <i>Delnd</i>	952.8	✓	
27	1 pc	Antenna <i>new</i>	181.30	✓	
28	1 pc	Rear buzzer <i>new</i>	187.60	✓	
Sub-Total:			8,478.90	204.00	0.00
			20%	0%	0%
After Less %:			6,783.12	204.00	0.00

6447-90

S.N: 370

5158.32

	Labour	
1	To dismantle damaged parts, straighten & welding.	1,400.00 700
2	To spray painting.	1,200.00 700
3	To remove & refit upholstery to facilitate repair	100.00 60
4	To remove & refit rear windscreen	150.00 120
5	To remove & replace rear reverse sensor.	80.00 50
6	To remove & replace rear tail-gate device.	80.00 ✓
7	To re-set electrical system & rear reverse sensor	180.00 180 X
8	To check wiring.	100.00 30
9	To re-seal anti-rust.	100.00 60
	Sub-Total:	3,390.00
	Total:	10,377.12
	After Less 20%:	8,301.70

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

Adrian Ling,
14/10/21.
05 Days.



8778 1999
24 hr accident call

Mobil 1



total: 7328.32
(P/P)
h/s: 581

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: