

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJU 5208G
 TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
 16 RAFFLES QUAY
 #24-01 HONG LEONG BUILDING
 SINGAPORE 048581

TEL: 68277660 FAX: 62257402

ATTN: Motor Claim Department

Estimate No: ES2290234/YISHUN
 Date: 12 Mar 2022
 Policy No: DMPCSN3017311902
 Veh Reg No: SJU5208G
 Make/Model: MITSUBISHI MIT.
 LANCER 1.5 MIVEC
 GLX AT ABS
 Chassis No: JMYSRCY2A9U004517
 Engine No: 4A910124039
 Reg. Date: 15/12/2009

WS Ref: TP/MSIG
 Claim Type: Third Party
 Accident Date: 08/10/2021
 TP Veh Reg No: SNA7766G

*Not Authorized
 U/P Rep @ 1850k
 Putty After Paint
 3 days*

Estimate Repair Cost to Vehicle No :SJU5208G

Description	U/Price	Quantity	List Price	Amount
			SS	SS
NETT				
1 FRONT BUMPER <i>810</i>	810.00	1 PC	810.00	<i>✓</i>
2 FRONT BUMPER REINFORCEMENT <i>326</i>	326.00	1 PC	326.00	<i>✓</i>
3 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	<i>✓</i>
4 LH HEADLAMP <i>691.00</i>	698.00	1 PC	698.00	<i>✓</i>
			1,855.00	
	Less 10%		185.50	1,669.50
Labour				
5 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMP,TO KNOCK & REPAIR FRT LH FENDER AND REALIGN THE SAME	400.00	1 LA	400.00	<i>300</i>
6 PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT AND FRT LH FENDER	500.00	1 LA	500.00	<i>400</i>
			900.00	900.00
			Total	SS 2,569.50
			Add GST @ 7%	179.87
			Total Amount Payable	SS 2,749.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE