



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA			Ref: CC4/ASM21010539/Ugs3q2 Date: 01/12/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8496P	Veh. Inspected	GBH 3230S	
Policy No.	P2419138	Coverage (\$)	0.00	
Claim No.	S1M03HUM	Excess (\$)	0.00	
Assign From		Assign Date	13/10/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFAT35Y80K210112	Colour	WHITE	
Odometer	204559 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MAXMILER	6 mm	
L/H Front Tyre	195 R15	MAXMILER	6 mm	
R/H Rear Tyre	195 R15 (D)	MAXMILER	6/6 mm	
L/H Rear Tyre	195 R15 (D)	MAXMILER	6/6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/09/2021	Inspection Date	13/10/2021	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	