

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

India International Insurance Pte Ltd

64 , Cecil Street # 04 - 05
 IOB Building
 Singapore 049711
 Tel : 6347 - 6100
 Fax : 6224 - 4174

Quotation

DATE : 13.10.2021
 VEH NO : SDA6063B
 MODEL : Nissan Sunny
 D O A : 12.10.2021
 YR REF : CB7666L

Cecilia

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SDA6063B (NISSAN SUNNY)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	627 ✓
2	Rear Bumper Clips <i>re</i>	1	40 ✓
3	Rear Bumper Side Holder - LH & RH <i>Dmg</i>	2	71 ✓
4	Rear Bumper Side Protector - RH <i>crackd</i>	1	224 ✓
5	Tail Lamp - RH <i>crackd</i>	1	332 ✓
6	Tail Lamp Lower Apron <i>Dehd</i>	1	85 ✓
7	Rear End Panel <i>Repair</i>	1	535 +
8	Reverse Sensor <i>Dmgd</i>	1	280 ✓
			<i>200(SN).</i>
	LABOUR CHARGE		
1	To knocking & pull out rear portion & renew above parts	\$	600.00 <i>400</i>
2	To putty & spray up paint works (front)	\$	600.00 <i>450</i>
3	To check wiring	\$	50.00 <i>30</i>
4	To spray tuff coat	\$	150.00 <i>40</i>
5	To remove reverse sensor	\$	100.00 <i>50</i>

1379
1241.10
S.N: 200

Total Labour \$ 1,500.00

Grand Total **\$ 1,500.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items to be replaced is subject to final approval from Insurance Company

NOTE :-

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN

Acknowledged by Repairer
 Signature:
 Date:

Total: 2421.10
45: 1.9K
03 Days