

SMRT Vehicle Repair Estimate

Group : Buses / Taxis / Private Car

Reg. No. : SKX3559D

Make / Model : MITSUBISHI LANCER

Chassis No :

Name of Driver :

Date/Time of Accident :

Surveyor is Required ? **YES** / NO

If Yes, VICOM / LKK / AIS / Others MSIG **AXA**

Vehicle is Towed Back ? **YES** / NO Date / Time :

Accident reporting date :

Type of Accident : Skid / Head-Rear / **Head-On** / Side Swipe / Others

Special Instruction to ARC, if any :


Ref. No.

Reg. Date :

Mileage

Rental/Replacement Vehicle : **Yes** / No

The damages on the vehicle are as indicated in the following diagram :



Signed :

Date :

Accident Repair Job Card No : Date Prepared :

Summary of Repair Estimates Repair Completed :

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges :	\$ 1,800.00	\$ -
------------------------	-------------	------

Total Spray Painting Charges :	\$ 3,300.00	\$ -
--------------------------------	-------------	------

Total Material Charges :	\$ 19,377.05	\$ -
--------------------------	--------------	------

Other Charges :	\$ 740.00	\$ -
-----------------	-----------	------

TOTAL :	\$ 25,217.05	\$ -
----------------	--------------	------

Lump Sum Repair, if any :

No. of Repair Days : [14] days [] days

Signature : Prepared by:

Adjusted by:

QN No. Invoice No.

Signed : Date :

Job Scope	Quotation from ARC	
To renew damaged parts , , cutting , welding , knocking , realign chassis , etc	\$ 1,800.00	
Total Labour Cost	\$ 1,800.00	\$ -

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	
To respray front bumper	\$ 250.00	\$
To respray front hood	\$ 250.00	\$
To respray fender RH	\$ 250.00	\$
To spray fender LH	\$ 250.00	\$
To spray support panel	\$ 250.00	\$
To spray Front door RH	\$ 250.00	\$
To respray Front door Lh	\$ 250.00	\$
To Respray rear fender RH	\$ 250.00	\$
To respray rear fender Lh	\$ 250.00	\$
To respray rear end panel	\$ 250.00	\$
To respray rear bumper	\$ 250.00	\$
To respray rear bootlid	\$ 250.00	\$
To respray chassis	\$ 300.00	\$
		\$
Spray Painting	\$ 3,300.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Page ()

Job Scope	Quotation from ARC	
Remove & refix air con and top up gas	\$ 80.00	
Reset system function	\$ 150.00	
To remove & refix shock absorber /undercarriage	\$ 250.00	
To apply anti rust	\$ 180.00	
Wheel alignment	\$ 80.00	
Total Other Costs	\$ 740.00	

Part 4 - Spare Parts / Material Usage

To be completed by Service Advisor, ARC							
Part Number	Parts Description	Qty	Nett price (\$)	Less	Final Price (\$)	Repair (R) Replace (/)	Not given (X) Repair (R) Replace (/)
	BONNET	1	\$ 783.00	10%	861.30		
	BONNET HINGE RH	1	\$ 52.00	10%	57.20		
	BONNET HINGE LH	1	\$ 52.00	10%	57.20		
	Bonnet inner rubber	1	\$ 35.00	10%	38.50		
	BONNET INSULATOR	1	\$ 155.00	10%	170.50		
	BONNET LOCK lower	1	\$ 128.00	10%	140.80		
	BONNET CABLE	1	\$ 101.00	10%	111.10		
	BONNET STOPPER	2	\$ 20.00	10%	44.00		
	SUPPORT PANEL	1	\$ 702.00	10%	772.20		
	SUPPORT PANEL GARNISH	1	\$ 128.00	10%	140.80		
	SUPPORT PANEL lower member frt	1	\$ 472.00	10%	519.20		
	SUPPORT PANEL TOP GARNISH	1	\$ 121.00	10%	133.10		
	support panel top garnish clip frt	10	\$ 3.30	10%	36.30		
	brace panel	1	\$ 74.50	10%	81.95		
	NUMBER PLATE	1	\$ 35.00	10%	38.50		
	NUMBER PLATE HOLDER	1	\$ 35.00	10%	38.50		
	NUMBER PLATE BASE	1	\$ 162.00	10%	178.20		
	BUMPER FRONT	1	\$ 743.00	10%	817.30		
	Bumper beam	1	\$ 168.00	10%	184.80		
	BUMPER CLIP	8	\$ 3.50	10%	30.80		
	BUMPER FOG LAMP COVER FRT RIGHT	1	\$ 101.00	10%	111.10		
	BUMPER FOG LAMP COVER FRT LEFT	1	\$ 101.00	10%	111.10		
	BUMPER FOG LAMP FRT RIGHT	1	\$ 250.00	10%	275.00		
	BUMPER FOG LAMP FRT LEFT	1	\$ 250.00	10%	275.00		
	BUMPER LOWER GRILE FRONT	1	\$ 195.00	10%	214.50		
	BUMPER REINFORCEMENT	1	\$ 297.00	10%	326.70		
	BUMPER RETAINER RH	1	\$ 35.00	10%	38.50		
	BUMPER RETAINER LH	1	\$ 35.00	10%	38.50		
	BUMPER BRACKET RH	1	\$ 74.00	10%	81.40		
	BUMPER BRACKET LH	1	\$ 74.00	10%	81.40		
	RH BUMPER LOWER SIDE LIP	1	\$ 320.00	10%	352.00		
	LH BUMPER LOWER SIDE LIP	1	\$ 320.00	10%	352.00		
	BUMPER TOWING COVER	1	\$ 35.00	10%	38.50		
	BUMPER SPOILER	1	\$ 450.00	10%	495.00		
	HEADLAMP LH	1	\$ 648.00	10%	712.80		
	HEADLAMP RH	1	\$ 648.00	10%	712.80		
	GRILLE FRONT	1	\$ 378.00	10%	415.80		
	GRILLE EMBLEM	1	\$ 62.00	10%	68.20		
	FRONT FENDER RH	1	\$ 378.00	10%	415.80		
	FRONT FENDER LH	1	\$ 378.00	10%	415.80		
	FRONT FENDER INNER SHIELD RH	1	\$ 100.00	10%	110.00		
	FRONT FENDER INNER SHIELD LH	1	\$ 100.00	10%	110.00		
	AIR CON CONDENSER	1	\$ 648.00	10%	712.80		
	AIR CON DISCHARGE HOSE	1	\$ 148.00	10%	162.80		
	AIR CON FAN	1	\$ 130.00	10%	143.00		
	AIR CON MOTOR	1	\$ 130.00	10%	143.00		
	AIR CON BLADE	1	\$ 75.00	10%	82.50		
	AIR CON DRYER LIQUID PIPE	1	\$ 168.00	10%	184.80		
	AIR CON CONDENSER FAN MOTOR	1	\$ 220.00	10%	242.00		

	RADIATOR	1	\$	780.00	10%	858.00		
	RADAI TOR FAN BLADE	1	\$	128.00	10%	140.80		
	RADIATOR COWLING	1	\$	200.00	10%	220.00		
	RADAI TOR FAN MOTOR	1	\$	162.00	10%	178.20		
	RADIATOR HOSE BOTTOM	1	\$	38.00	10%	41.80		
	RADIATOR SPARE TANK	1	\$	115.00	10%	126.50		
	RADIATOR TOP BRACKET LH	1	\$	48.00	10%	52.80		
	RADIATOR TOP BRACKET RH	1	\$	48.00	10%	52.80		
	AIR CLEANER AIR DUCT	1	\$	168.00	10%	184.80		
	AIR CLEANER BOX	1	\$	263.00	10%	289.30		
	WIPER WASHER TANK	1	\$	162.00	10%	178.20		
	Wiper washer tank cap	1	\$	20.00	10%	22.00		
	wiper washer tank motor	1	\$	88.00	10%	96.80		
	engine top cover	1	\$	350.00	10%	385.00		
	Front Windscreen	1	\$	750.00	10%	825.00		
	front windscreen moulding	1	\$	180.00	10%	198.00		
	front windscreen glum	1	\$	60.00	10%	66.00		
	Front meter box	1	\$	980.00	10%	1078.00		
	Air Cleaner hose	1	\$	250.00	10%	275.00		
	Top Radiator hose	1	\$	120.00	10%	132.00		
	Lower Radiator hose	1	\$	110.00	10%	121.00		
	Compressor	1	\$	850.00	10%	935.00		
	Pulley	1	\$	380.00	10%	418.00		
	Spare tank	1	\$	200.00	10%	220.00		
	Wiper tank	1	\$	220.00	10%	242.00		
	Front bumper lower cover	1	\$	150.00	10%	165.00		
TOTAL MATERIALS					-	\$ 19,377.05		

Surveryor Remark: