

# 威利摩多 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.  
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

12 OCT 2021

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 Shenton Way  
#09-16 AIG Building  
Singapore 079120

*Not Authorised*  
*1/10/21*  
*Preserving After Repair*  
*6 days*

Attn: Motor claim dept-3<sup>rd</sup> party claim  
Claiming against your insured vehicle no: SLJ6974E  
Accident involving vehicle no: SKS1206L/SLJ6974E  
DOA: 12/10/2021 at ANG MO KIO STREET 32 SINGAPORE

Dear officer in charge

Estimate cost of repair for vehicle no: SKS1206L

To supplied:

| Description                  | Qty | Amount                  |   |
|------------------------------|-----|-------------------------|---|
| Bonnet                       | 1   | R <sub>1</sub> 1028.10  | ✓ |
| Bonnet lock                  | 1   | R <sub>1</sub> 178.40   | ✓ |
| Bonnet hinge                 | 1   | R <sub>1</sub> 59.90    | ✓ |
| Support panel                | 1   | R <sub>1</sub> 977.60   | ✓ |
| Aircon condenser             | 1   | 1,404.30                | ? |
| Radiator                     | 1   | 1,764.00                | ? |
| Fan motor                    | 1   | S <sub>2</sub> 580.10   | X |
| Fan blade                    | 1   | S <sub>2</sub> 190.20   | X |
| Fan cowling                  | 1   | S <sub>2</sub> 278.10   | X |
| Front grille w chrome        | 1   | CM 379.10               | ✓ |
| Headlamp HID                 | 2   | M <sub>3</sub> 5,608.00 | ✓ |
| Headlamp top chrome moulding | 2   | 275.40                  | 2 |
| Front bumper                 | 1   | BT/CM 458.00            | ✓ |
| Front bumper enforcement     | 1   | 379.20                  | ? |
| Front bumper retainer        | 2   | DIY 164.60              | ✓ |
| Front fender                 | 2   | R 1,522.80              | ? |
| Fender cowling LH&RH         | 2   | S <sub>2</sub> 326.80   | X |
| Cowling clip                 | 1   | M <sub>2</sub> 38.00    | X |
| Bumper lower grille          | 1   | R <sub>2</sub> 122.80   | ✓ |
| Lower grille                 | 1   | 128.40                  | ? |
| Foglamp                      | 2   | S <sub>2</sub> 496.40   | X |
| Foglamp cover                | 2   | O/S 225.80              | ✓ |

|                            |    |           |   |
|----------------------------|----|-----------|---|
| Brace panel                | 1  | 190.20    | ✓ |
| Engine lower center cover  | 1  | 135.80    | ✓ |
| Engine lower side cover RH | 1  | 153.50    | ✓ |
| Engine lower side cover LH | 1  | 131.10    | X |
| Clip                       | 20 | 76.00     | ✓ |
| Parts                      |    | 17,272.60 |   |
| Parts less 25%             |    | 12,954.45 |   |

250.00 100%

To remove/replace radiator, aircon condenser, fan assy. Recharge aircon gas

To remove damage parts and attachments

Cut and weld damaged front panel and fender

Straighten front chassis where necessary

Replace / align all parts into position

To spray paint

1,100.00  
1,300.00  
-----  
15,604.45