

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

13-Oct-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6727 L

1 pc	Boot lid	\$	1,119.00 Def
1 pc	Boot lid lock	\$	99.00 XSVC
1 pc	Bootlid lock cable	\$	35.00 XSVC
1 pc	Bootlid striker	\$	21.00 XSVC
1 pc	Bootlid emblem	\$	27.00 / nec
1 pc	Bootlid CRDi	\$	29.00 / nec
1 pc	Boot lid rubber weatherstrip	\$	96.00 XSVC
1 pc	Boot lid lower garnish	\$	290.00 / cut
2 pcs	Bootlid hinges @ \$66.00	\$	132.00 XR
1 pc	Bootlid inner trim	\$	190.00 XSVC
2 pcs	Bootlid rear license plate lamps @ \$30.00	\$	60.00 XSVC
1 pc	End panel inner garnish	\$	74.00
1 pc	End panel	\$	250.00 1/4 Def
1 pc	Spare tyre clamp	\$	8.00 ?
1 pc	Rear bumper	\$	696.00 / cut
1 pc	Rear bumper lower cover	\$	206.00 / cut
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 / nec
1 pc	Rear bumper inner sponge	\$	114.00 ?
1 pc	Rear bumper reinforcement	\$	607.00 ?
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00 / nec
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 ?
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 ?
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00 o/s 46
2 pcs	Rear o/s air vent @ \$30.00	\$	60.00 / mis
2 pcs	Rear n/s & o/s tail lamps	\$	842.00 o/s 421
2 pcs	Bootlid n/s & o/s reflector @ \$350.00	\$	700.00 o/s 350
2 pcs	n/s & o/s tail lamp panel @ \$215.00	\$	430.00 o/s 215
1 pc	Floorboard panel	\$	625.00 XR
1 pc	Floorboard panel trim	\$	205.00 XSVC
1 pc	Exhaust pipe	\$	1,009.00 ?
1 pc	Exhaust pipe hanger	\$	28.00 ?
1 pc	Rear o/s fender	\$	1,205.00 Def
1 pc	Rear o/s fender top chrome moulding	\$	97.00 ?
1 pc	Rear o/s fender inner shield	\$	120.00 XSVC

1 pc	Rear windscreen	\$	801.00	X Svc
1 pc	Rear windscreen moulding	\$	87.00	/nec
		\$	10,592.00	
	Less 10%	\$	1,059.20	
		\$	9,532.80	

S/NETT

1 set	Rear bumper clips	\$	48.00	/nec
1 set	End panel inner garnish clips	\$	30.00	/nec
1 set	Bootlid inner trim clips	\$	52.00	X Svc
1 set	Bootlid lower garnish clips	\$	60.00	X Svc
1 set	Bootlid stickers	\$	100.00	/nec
1 set	Reverse sensor	\$	280.00	?
1 pc	Rear bumper top protector	\$	80.00	/cut
1 pc	Rear o/s fender sticker	\$	60.00	/nec
1 set	Floorboard compartment insulating paddings	\$	120.00	X Svc
1 set	Rear o/s door stickers	\$	100.00	/nec
1 set	Sealant	\$	50.00	/nec
1 pc	Rear number plate with casing	\$	50.00	X Svc
	Sundry	\$	50.00	X Svc
	To dismantle / refit rear exhaust pipe	\$	120.00	50
	Towing fee	\$	100.00	60
	To dismantle / refit rear new windscreen glass and moulding	\$	120.00	✓
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	40
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut end panel, floorboard compartment, rear o/s fender, rear n/s & o/s tail lamp panels. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	2,400.00	900
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, floorboard compartment, rear o/s fender, rear o/s tail lamp panels, rear o/s door	\$	1,800.00	1080
	To apply rustproofing on the repaired and replaced panels.	\$	250.00	50
		\$	15,702.80	

LKK Auto Consultants hence notify the Repairer to apply rustproofing on the repaired and replaced panels.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to firm quotation

ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Acknowledged by Repairer

Signature:

Date:

Thavan@lkhauto.com
82235769
13/10/21 .1415
5days wp
C/S after repair photo