

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 14 Oct 2021)

Parts: M1-MPV

TOYOTA PREVIA 2.4 7-seater (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJW4213L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE / BR	0	0.00	net *35.00 FS
2	1		*FRT BUMPER / BR	0.00	0.00	*280.00 F
3	2		*FRT BUMPER RETAINER / BR	0.00	0.00	*90.00 F
4	1		*FRT BUMPER LOWER GRILLE / BR	0.00	0.00	*120.00 F
5	1		*FRT BUMPER SPONGE / CR4	0.00	0.00	*70.00 F
6	1		*FRT BUMPER REINFORCEMENT / OD	0.00	0.00	*150.00 F
7	2		*FRT BUMPER SIDE GUIDE / X nn	0.00	0.00	*90.00 F
8	1		*FRT BUMPER TOWING COVER LH / m/j	0.00	0.00	*25.00 F
9	2		*FRT FOG LAMP / X nn	0.00	0.00	*260.00 F
10	2		*FRT FOG LAMP INNER BRACKET / X nn	0.00	0.00	*110.00 F
11	1		*FRT GRILLE / BR	0.00	0.00	*240.00 F
12	1		*FRT GRILLE EMBLEM / CR4	0.00	0.00	*45.00 F
13	1		*FRT GRILLE TOP GARNISH / CR4	0.00	0.00	*150.00 F
14	10		*FRT GRILLE TOP GARNISH CLIP / H/c	0.00	0.00	*15.00 F
15	1		*FRT BONNET / OD	0.00	0.00	*240.00 F
16	2		*FRT BONNET HINGE / BT	0.00	0.00	*80.00 F
17	1		*FRT BONNET STAND / X nn	0.00	0.00	*35.00 F
18	1		*FRT BONNET STAND CLIP / X nn	0.00	0.00	*1.50 F
19	1		*FRT BONNET SEAL / X nn	0.00	0.00	*40.00 F
20	1		*FRT BONNET INSULATOR / CR4	0.00	0.00	*150.00 F
21	10		*FRT BONNET INSULATOR CLIP / H/c	0.00	0.00	*15.00 F
22	1		*FRT BONNET LOCK / BT	0.00	0.00	*55.00 F
23	1		*FRT FENDER INNERSHIELD / (RH) TM	0.00	0.00	*200.00 F 100
24	20		*FRT FENDER INNERSHIELD CLIP / H/c	0.00	0.00	19 *30.00 F
25	2		*FRT HEADLAMP / BR	0.00	0.00	*800.00 F
26	1		*FRT UPPER SUPPORT / OD	0.00	0.00	*180.00 F
27	1		*FRT LOWER SUPPORT / OD	0.00	0.00	*150.00 F
28	1		*FRT SIDE SUPPORT / (RH) BT (LH) BT	0.00	0.00	152 *300.00 F
29	1		*FRT BRACE PANEL / BT	0.00	0.00	*45.00 F
30	1		*FRT HORN / X nn	0.00	0.00	*65.00 F
31	1		*AIRCON CONDENSER / OD	0.00	0.00	*480.00 F
32	1		*AIRCON FAN BLADE / BR	0.00	0.00	*70.00 F
33	1		*AIRCON FAN MOTOR / Jammed	0.00	0.00	*180.00 F
34	1		*RADIATOR ASSY / BT	0.00	0.00	*580.00 F
35	1		*RADIATOR FAN MOTOR / Jammed	0.00	0.00	*180.00 F
36	1		*FAN COWLING / BR	0.00	0.00	*120.00 F
37	1		*AIR INLET CLEANER NO.1 / CR4	0.00	0.00	*70.00 F
38	1		*AIR INLET CLEANER NO.2 / X nn	0.00	0.00	*70.00 F
39	1		*RESONATOR ASSY / BR	0.00	0.00	*120.00 F
40	1		*COOLANT / H/c	0	0.00	net *40.00 FS
41	2		*FRT BUMPER REINFORCEMENT BRACKET / X nn	0.00	0.00	*140.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)

6,116.50

+ Margin on L,N Items 10.00% (\$\$)

604.15

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	30.00✓
2	TOP UP AIRCON GAS	New	100.00✓
3	TO KNOCK FRT FENDER X2, WELD,REMOVE & FIX ON ABOVE PARTS	New 1000	1,200.00
4	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00✓
5	TO DIAGNOSE & RESET FAULT CODE	New	X 180.00
Gross Labour Cost (\$\$)			2,510.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >