



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2108724

INV Date 20/12/2021

Reference CC4/LPC21010560/Ves3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SHA 964T
Insured Veh. YN 7605P
Claim No. 21/21/21/VC00/025036
Policy No. Z/21/VC00/109811
Accident Date 13/10/2021
Inspection Date 14/10/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21010560/Ves3q2 Date: 20/12/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 7605P	Veh. Inspected	SHA 964T
	Policy No.	Z/21/VC00/109811	Coverage (\$)	0.00
	Claim No.	21/21/21/VC00/025036	Excess (\$)	0.00
	Assign From	ONG LI LI	Assign Date	13/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTDKB3FU903538631	Colour	YELLOW
	Odometer	656909 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/10/2021	Inspection Date	14/10/2021
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 964T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	499.90	499.90
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER LOWER COVER	SERVICEABLE	552.60	-
2	REAR BUMPER UNDER SIDE COVER LH/RH @\$232.00	O/S CUT	464.00	232.00
1	REAR BUMPER UNDER SIDE CENTRE COVER	SCRATCHED	552.60	552.60
1	REAR BUMPER TOWING COVER	SCRATCHED	82.70	82.70
2	REAR BUMPER SIDE RETAINER LH RH @\$94.80	SERVICEABLE	189.60	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
2	REAR BUMPER SIDE EXTENSION LH RH @\$148.40	TO REPAIR SEE LABOUR	296.80	-
2	REAR BUMPER ARM ASSY LH RH @\$139.60	SERVICEABLE	279.20	-
1	REAR END PANEL	SERVICEABLE	602.10	-
1	REAR END PANEL GARNISH	SERVICEABLE	165.80	-
1	REAR WINDSCREEN GLASS WITH MOULDING	SERVICEABLE	1,778.30	-
1	BACK DOOR GARNISH SUB ASSY	DEFORMED	889.70	889.70
1	REAR TRUNK LID COVER	TO REPAIR SEE LABOUR	1,126.60	-
1	REAR TRUNK LID LOCK	TO REPAIR SEE LABOUR	457.90	-
1	REAR TRUNK LID GLASS	SERVICEABLE	1,569.70	-
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
2	REAR TRUNK LID HINGE LH RH	SERVICEABLE	189.50	-
2	REAR TRUNK LID ABSORBER LH RH	SERVICEABLE	287.50	-
1	ROOF TOP CENTER COVER -BLACK	MISSING	956.30	956.30
1	ROOF TOP GARNISH SUB LH	MISSING	136.80	136.80
1	ROOF TOP GARNISH SUB RH	MISSING	136.80	136.80
	LESS 25% DISCOUNT		-2,930.33	-918.73
			8,790.97	2,756.17

Report Ref No. CC4/LPC21010560/Ves3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR FENDER ADVERTISEMENT LOGO LH (SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	100.00	100.00
1	REAR NUMBER PLATE WITH TRIM COVER (SN)	NECESSARY	55.00	55.00
1	REAR TRUNK LID COMFORT & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR REVERSE SENSOR (SN)	CUT	135.70	135.70
			540.70	540.70
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER SIDE EXTENSION LH RH,REAR TRUNK LID COVER AND REAR TRUNK LID LOCK .		1,400.00	700.00
	SPRAY PAINTING CHARGE.		800.00	625.00
	CHECK ALL LIGHTING.		60.00	20.00
	TUFF KOTE.		80.00	30.00
	REMOVE/REFIX REVERSE SENSOR .		60.00	20.00
	REMOVE/REFIX REAR WINDSCREEN GLASS .	NOT NECESSARY	120.00	-
			2,520.00	1,395.00
GRAND TOTAL			11,851.67	4,691.87
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,750.00

Report Ref No. CC4/LPC21010560/Ves3q2

THEVAN THOMAS KARTHIKESAVAN

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 964T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHA 964T

RE-INSPECTION

