



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SINGAPORE CIVIL DEFENCE FORCE (MHA05)			Ref:	CS/SCD21010565/R1vf3e2
91 UBI AVE 4 SINGAPORE 408827			Date:	28/10/2021
ATTN: JAMIN TAN			Code:	SCD
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.		Veh. Inspected	QX 1169M
	Policy No.	MHASCD06000082533	Coverage (\$)	0.00
	Claim No.	ACC-IND-21-21	Excess (\$)	0.00
	Assign From	JAMIN TAN	Assign Date	14/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	FORD	c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	WF06XXGCC6GA20872	Colour	WHITE
	Odometer	37610 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	SUMMERSTAR	6 mm
	L/H Front Tyre	205/55 R16	SUMMERSTAR	6 mm
	R/H Rear Tyre	205/55 R16	SUMMERSTAR	6 mm
	L/H Rear Tyre	205/55 R16	SUMMERSTAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date		Inspection Date	18/10/2021
	Survey held at	K & S BODYWERK ENGINEERING PTE LTD 2B SUNGEI KADUT DRIVE,#01, SINGAPORE 729555		
5a. Remarks				

Registration No. QX 1169M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Glass window	1	Cracked			
1.2	Rear door glass solar file	1	Necessary			
1.3	Rear door glass sealant	1	Necessary			
1.4	Rear door frame	1	Bent			
1.5	Rear door handle	1	Cracked			
1.6	Rear door moulding	1	Necessary			
1.7	Rear door insulator	1	Necessary			
1.8	Rear door panel retainer	2	Deformed			
1.9	Rear door emblem (Focus)	1	Necessary			
1.10	Rear door emblem (Ford)	1	Necessary			
1.11	Rear door tailgate trim	1	Cracked			
1.12	Rear door back panel trim	1	Cracked			
1.13	Rear door upper lock	1	Bent			
1.14	Rear door lower lock	1	Bent			
1.15	Rear door wiper motor assy	1	Not Necessary			
1.16	Rear door frame rubber seal	1	Necessary			
1.17	Rear R/H door signal lamp	1	Cracked			
1.18	Rear L/H door signal lamp	1	Cracked			
1.19	Rear L/H panel signal lamp	1	Cracked			
1.20	Rear number plate lamp	1	Missing			
1.21	Rear number plate	1	Missing			
1.22	Switch assembly	1	Missing			
1.23	Rear bumper	1	Deformed			
1.24	Rear bumper bracket	1	Cracked			
1.25	Rear bumper reflector	2	Not Necessary			
1.26	Rear floor cross member	1	Bent			
1.27	Rear door absorber bracket	4	Not Necessary			

1.28	Rear door sticker	1	Necessary			
2	LABOUR					
2.1	Replace rear door glass					4
2.2	Replace rear door glass solar film					2
2.3	Water seepage for rear door glass					1
2.4	Remove & replace rear door frame					4
2.5	Replace rear door panel					1
2.6	Replace rear door panel retainer					1
2.7	Replace rear door emblem					0.5
2.8	Replace rear R/H door garnish					0.5
2.9	Replace rear L/H door garnish					0.5
2.10	Replace rear door trim					1
2.11	Replace rear door upper lock					1
2.12	Replace rear door lower lock					1
2.13	Replace dislodged rear door wiper assy					2
2.14	Replace rear door frame rubber seal					0.5
2.15	Replace rear R/H door signal lamp					0.5
2.16	Replace rear L/H door signal lamp					0.5
2.17	Replace rear L/H panel signal					0.5
2.18	Replace dislodged rear number plate					0.5
2.19	Replace dislodged rear number plate lamp					0.5
2.20	Remove & replace rear bumper					2
2.21	Replace rear bumper retainer					1
2.22	Panel beat dented spare tyre booth					8
2.23	Re-align rear chassis					8
2.24	Wiring for all replacement lighting & wiper					4
2.25	Putty & spray rear door & rear LH panel					6
2.26	Replace rear door sticker					2
		TOTAL PARTS COST				
		TOTAL MAN-HOUR				53.5

Registration No. QX 1169M

Registration No. QX 1169M

Vehicle Inspected By:



MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor



ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. QX 1169M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

