

Registration No. QX 1169M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Glass window	1	Cracked			
1.2	Rear doo glass solar file	1	Necessary			
1.3	Rear door glass sealant	1	Necessary			
1.4	Rear door frame	1	Bent			
1.5	Rear door handle	1	Necessary			
1.6	Rear door moulding	1	Necessary			
1.7	Rear door insulator	1	Necessary			
1.8	Rear door panel retainer	2	Necessary			
1.9	Rear door emblem (Focus)	1	Necessary			
1.10	Rear door emblem (Ford)	1	Necessary			
1.11	Rear door tailgate trim	1	Cracked			
1.12	Rear door back panel trim	1	Cracked			
1.13	Rear door upper lock	1	Bent			
1.14	Rear door lower lock	1	Bent			
1.15	Rear door wiper motor assy	1	Not Necessary			
1.16	Rear door frame rubber seal	1	Necessary			
1.17	Rear R/H door signal lamp	1	Cracked			
1.18	Rear L/H door signal lamp	1	Cracked			
1.19	Rear L/H panel signal lamp	1	Cracked			
1.20	Rear number plate lamp	1	Missing			
1.21	Rear number plate	1	Missing			
1.22	Switch assembly	1	Missing			
1.23	Rear bumper	1	Dented			

1.24	Rear bumper bracket	1	Cracked			
1.25	Rear bumper reflector	2	Not Necessary			
1.26	Rear floor cross member	1	Bent			
1.27	Rear door absorber bracket	4	Not Necessary			
1.28	Rear door sticker	1	Necessary			
2	LABOUR					
2.1	Replace rear door glass					4
2.2	Replace rear door glass solar film					2
2.3	Water seepage for rear door glass					1
2.4	Remove & replace rear door frame					4
2.5	Replace rear door panel					1
2.6	Replace rear door panel retainer					1
2.7	Replace rear door emblem					0.5
2.8	Replace rear R/H door garnish					0.5
2.9	Replace rear L/H door garnish					0.5
2.10	Replace rear door trim					1
2.11	Replace rear door upper lock					1
2.12	Replace rear door lower lock					1
2.13	Replace dislodged rear door wiper assy					2
2.14	Replace rear door frame rubber seal					0.5
2.15	Replace rear R/H door signal lamp					0.5
2.16	Replace rear L/H door signal lamp					0.5
2.17	Replace rear L/H panel signal					0.5
2.18	Replace dislodged rear number plate					0.5
2.19	Replace dislodged rear number plate lamp					0.5
2.20	Remove & replace rear bumper					2
2.21	Replace rear bumper retainer					1
2.22	Panel beat dented spare tyre booth					8
2.23	Re-align rear chassis					8

2.24	Wiring for all replacement lighting & wiper					4
2.25	Putty & spray rear door & rear LH panel					6
2.26	Replace rear door sticker					2
		TOTAL PARTS COST				
		TOTAL MAN-HOUR				53.5