

08/11/13) wef

ASS. REC. BY: *Pasm*

REF:

CS/SCD21010565/RIVf3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *QX 1169M*at Workshop m/s *K & S Body work*of *No. 2 JB Sunhel Kadut DR*Insured: *SCD*

Policy No.

Claims No. MHASCD06000082533

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

21/10/21

Submit ManHR 53.50

Veh No:

*QX 1169M*

Yr Regn:

/ -

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

*FORD*

C.C

Colour

*WHITE*

A/C: Insured / Std / NI / NA

Sp. Reading

*037610*

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*WF06XXGCC69A20872*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

*205/55R16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

*Summer*

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

*11/10/21* UNKNOWN

D.O.I.

*18/10/21*

Survey held at

*K & S Body work*Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 21/10/21-typist

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

); S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



**Scope of Work**  
**Home Team Agency**  
**SCDF Reference No : ACC-IND-21-21**  
**Indeco Reference No: SCDF/2021/10/14**

**SCOPE OF WORK**

- 1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

VEHICLE TYPE	FRC	REGISTRATION NO	QX 1169 M	REPAIR TYPE	ACCIDENT
MAKE/MODEL	FORD FOCUS	UNIT	STN 12	CONTRACTOR	INDECO

S/N	ITEM DESCRIPTION	PARTS					LABOUR		
		PARTS QTY	PARTS COST PER UNIT (\$)	MARK UP RATE	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	MAN-HOUR RATE (\$)	MAN-HOUR QTY	TOTAL MAN-HOUR COST (\$)
SCOPE OF REPAIRS									
A	Labour								
1	Replace rear door glass							4	
2	Replace rear door glass solar firm							2	
3	Water seepage for rear door glass							1	
4	Remove & replace rear door frame							4	
5	Replace rear door panel							1	
6	Replace rear door panel retainer							1	
7	Replace rear door emblem							0.5	
8	Replace rear R/H door garnish							0.5	
9	Replace rear L/H door garnish							0.5	
10	Replace rear door trim							1	
11	Replace rear door upper lock							1	
12	Replace rear door lower lock							1	
13	Replace dislodged rear door wiper assy							2	
14	Replace rear door frame rubber seal							0.5	
15	Replace rear R/H door signal lamp							0.5	
16	Replace rear L/H door signal lamp							0.5	
17	Replace rear L/H panel signal							0.5	
18	Replace dislodged rear number plate							0.5	
19	Replace dislodged rear number plate lamp							0.5	
20	Remove & replace rear bumper							2	
21	Replace rear bumper retainer							1	
22	Panel beat dented spare tyre booth							8	
23	Re-align rear chassis							8	
24	Wiring for all replacement lighting & wiper							4	
25	Putty & spray paint rear door & rear LH panel							6	
26	Replace rear door sticker							2	
SUB TOTAL								53.5	\$0.00
B	Materials								
1	Glass Window <i>cm</i>	1						NA	
2	Rear door glass solar firm <i>ne</i>	1						NA	
3	Rear door glass sealant <i>m</i>	1						NA	
4	Rear door frame <i>bt</i>	1						NA	
5	Rear door handle <i>cm</i>	1						NA	
6	Rear door moulding <i>ne</i>	1						NA	
7	Rear Door Insulator <i>ne</i>	1						NA	
8	Rear door panel retainer <i>de</i>	2						NA	
9	Rear door emblem (Focus) <i>ne</i>	1						NA	
10	Rear door emblem (Ford) <i>ne</i>	1						NA	
11	Rear door tailgate trim <i>cm</i>	1						NA	
12	Rear door back panel trim <i>cm</i>	1						NA	
13	Rear door upper lock <i>bt</i>	1						NA	
14	Rear door lower lock <i>bt</i>	1						NA	
15	Rear door wiper motor assy <i>TX</i> <i>nn</i>	1						NA	
16	Rear door frame rubber seal <i>ne</i>	1						NA	
17	Rear R/H door signal lamp <i>cm</i>	1						NA	
18	Rear L/H door signal lamp <i>cm</i>	1						NA	
19	Rear L/H panel signal lamp <i>cm</i>	1						NA	
20	Rear number plate lamp <i>mis</i>	1						NA	
21	Rear number plate <i>ms</i>	1						NA	
22	Switch Assembly <i>mis</i>	1						NA	
23	Rear bumper <i>de</i>	1						NA	
24	Rear bumper bracket <i>cm</i>	1						NA	



25	Rear bumper reflector	nn	2						NA
26	Rear floor cross member	67	1						NA
27	Rear door absorber bracket	nn	4						NA
28	Rear door sticker		1						NA
<b>SUB TOTAL</b>									<b>\$0.00</b>
<b>C Collection &amp; Delivery</b>									
1	Collection From Station - Workshop (SOR 10)	not included		1	\$	70.59	\$	70.59	
2	Delivery From Workshop - Station (SOR 9)	not included		1	\$	46.12	\$	46.12	
<b>Total</b>									<b>\$116.71</b>
<b>D ADDITIONAL SERVICES</b>									
1	Admin Support			NA	\$0.00	0	\$0.00		
<b>SUB TOTAL</b>									<b>\$116.71</b>
<b>COSTING</b>				<b>TOTAL PARTS COST (AFTER MARK UP)</b>				<b>\$0.00</b>	
				<b>TOTAL MAN-HOUR COST</b>				<b>\$0.00</b>	
				<b>TOTAL ADMIN SUPPORT COST</b>				<b>\$0.00</b>	
				<b>TOTAL PARTS COST + TOTAL MAN-HOUR COST + ADMIN</b>				<b>\$116.71</b>	
<b>Contractor shall complete the entire repair within xx working days upon collection date of vehicle</b>									
<b>Contractor QC</b>			<b>Home Team QC / Fleet Manager / Appointed Surveyor</b>			<b>(Asst Dir for repairs &lt; \$5000 Director for repairs up to \$750,000)</b>			
Name			Name			Name			
Signature			Signature			Signature			
Date			Date			Date			
<b>Scope of Works must be verified by Home Team Contract Manager before works can begin</b>									
<b>Duration of Work</b>									
<b>Contractor</b>			<b>Contractor</b>			<b>Contractor QC</b>			
Date Vehicle Collected			Date Vehicle Completed			Name			
Signature			Signature			Signature			
Name			Name			Date			
<b>Verification of Completed Repairs</b>									
<b>Contractor QC</b>			<b>Home Team QC / Appointed Surveyor</b>			<b>Home Team Contract Manager / Fleet</b>			
Name			Name			Name			
Signature			Signature			Signature			
Date			Date			Date			
<b>All completed repairs must be verified by Home Team Contract Manager / Fleet Manager before payment can be made</b>									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pass  
Hp 90010068

6 days

P/P

18/10/21 @ 1000 hrs

Resurvey before paint