

VEHICLE DETAIL






Vehicle No	QX 1169 M	SCDF Ref. No.	ACC-IND-21-21
		Adar No	2361



REPAIR DESCRIPTIONS

- 1) Replace rear door glass (pic 1)
- 2) Replace rear door glass solar film (pic 1)
- 3) Water seepage for rear door glass (pic 1)
- 4) Remove & replace rear door frame (pic 2,3)
- 5) Replace rear door panel (pic 4)
- 6) Replace rear door panel retainer (pic 5)
- 7) Replace rear door emblem (pic 6,7)
- 8) Replace rear R/H door garnish (pic 8)
- 9) Replace rear L/H door garnish (pic 9)
- 10) Replace rear door trim (pic 10,11)
- 11) Replace rear door trim insulator (pic 12)
- 12) Replace rear door upper lock (pic 13)
- 13) Replace rear door lower lock (pic 14)
- 14) Replace dislodged rear door wiper assy (pic 15,16)
- 15) Replace rear door frame rubber seal (pic 17)
- 16) Replace rear R/H door signal lamp (pic 18)
- 17) Replace rear L/H door signal lamp (pic 19)
- 18) Replace rear L/H panel signal (pic 20)
- 19) Replace dislodged rear number plate (pic 21)
- 20) Replace dislodged rear number plate lamp (pic 22)
- 21) Remove & replace rear bumper (pic 23,24)
- 22) Replace rear bumper retainer (pic 23,24)
- 23) Panel beat dented spare tyre booth (pic 25)
- 24) Wiring for all replacement lighting & wiper
- 25) Putty & spray paint rear door & rear L/H panel (pic 1,2,20)
- 26) Replace rear door sticker (pic 2)

PHOTOS OF DAMAGED PARTS

Rear door glass shattered (pic 1)	Rear door dented (pic 2)
	
Rear door dented (pic 3)	Rear door panel dented (pic 4)
	

Rear door panel retainer dented (pic 5) 	Scratcher on rear door emblem (pic 6) 
Scratcher on rear door emblem (pic 7) 	Rear R/H door garnish crack (pic 8) 
Rear L/H door garnish crack (pic 9) 	Rear door trim dislodged (pic 10) 
Rear door trim dislodged (pic 11) 	Rear door trim insulator torn (pic 12) 
Rear door upper lock dented (pic 13) 	Rear door lower lock dented (pic 14) 
Rear door wiper dented (pic 15) 	Rear door wiper dislodged (pic 16) 
Rear door frame rubber seal torn (pic 17) 	Rear R/H signal lamp crack (pic 18) 

Rear L/H signal lamp crack (pic 19)	Rear L/H panel signal lamp crack (pic 20)
 Rear L/H signal lamp crack	 Rear L/H side signal lamp crack
Rear number plate dislodged (pic 21)	Rear number plate lamp dislodged (pic 22)
 Rear number plate dislodged	 Rear number plate lamp dislodged
Rear bumper crack (pic 23)	Rear bumper crack (pic 24)
 Rear bumper crack	 Rear bumper dented
Spare tyre booth dented (pic 25)	QX 1169 M
 Spare tyre booth dented	