

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0839/2021/JT
DATE : 12-Oct-21
WIP : 48626

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR NAGAR MEHUL HASMUKH
ADDRESS : 1 FORT ROAD
#15-03
SINGAPORE 439069
TELEPHONE : HP +65 94242099
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210105705
VEHICLE NO : **SNB 6228 U**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 31/8/2021
ENGINE NO : CZD C50059
CHASSIS NO : WAUZZZF34M1156915
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Oct-21
PLACE OF ACCIDENT : REPUBLIC PLAZA CAR PARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 6228 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	X ✓
2	TO RENEW RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.	S/N \$ 300.00	✓ ✓
3	TO INSTALL SOLAR FILM FOR RHS SIDE 1/4 GLASS.	S/N \$ 400.00	✓ ✓
4	TO CARRY OUT WATER SEEPAGE TEST ON 1/4 GLASS.	S/N \$ 200.00	152 ✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELETRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N \$ 1,600.00	✓ ✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRRAG. FTC	S/N \$ 1,600.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 4,460.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 6228 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280 ✓
8	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PART REMOVED	\$ 6,400.00	3500 4250
9	TO REPSRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, DRAIN CHANNEL, ROOF CHANEL, DOOR ENTRANCE AND REAR END PANEL FITTING.	\$ 7,000.00	2575 ✓ $(3.5 + 1) \times 550 = 2475$ Handle : 100 <u>2575</u>
10	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	+
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 18,732.00	

55-UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 6228 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER	1	\$ 1,634.00	+	
2	REAR BUMPER FIXING PARTS	1	\$ 211.00	+	
3	REAR BUMPER SPOILER	1	\$ 459.00	+	
4	REAR BUMPER BRACKET - RH	1	\$ 48.00	+	
5	REAR BUMPER REFLECTOR - RH	1	\$ 41.00	+	
6	REAR TAIL LIGHT - RH	1	\$ 926.00	+	
7	REAR BUMPER GUIDE SECTION - RH	1	\$ 63.00	+	
8	REAR WHEEL ARCH COVER - LH / RH	2	\$ 536.00	✓	428.80
9	REAR SECTIONAL PART - RH	1	\$ 3,388.00	✓	2710.40
10	1/4 GLASS	1	\$ 614.00	✓	490.80
11	PRIMER	1	\$ 20.00	✓	15.76
12	REAR WHEEL HOUSING LINER - RH	1	\$ 241.00	+	
13	REAR WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 101.00	+	
14	REAR WHEEL SPOILER	1	\$ 39.00	+	
15	REAR DOOR - RH	1	\$ 2,909.00	✓	2327.20
16	REAR DOOR OUTER SEAL - RH	1	\$ 135.00	✓	108
17	REAR DOOR ATTACHMENT PARTS	1	\$ 311.00	+	
18	REAR DOOR CATCH - RH	1	\$ 120.00	?	96
19	REAR DOOR SEAL INNER	1	\$ 191.00	+	
20	SILL PANEL SEAL - RH	1	\$ 135.00	?	X
SUB TOTAL SPARE PARTS			\$ 12,122.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 6228 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR LOWER COVER - RH <i>lit</i>	1	\$ 257.00 ✓	205.20
22	REAR DOOR HANDLE - RH <i>lit</i>	1	\$ 198.00 ✓	158
23	REAR DOOR HANDLE CAP - RH <i>lit</i>	1	\$ 27.00 ✓	21.60
24	REAR DOOR MOUNTING BAR - RH <i>lit</i>	1	\$ 162.00 +	
25	REAR DOOR BOWDEN CABLE - RH <i>lit</i>	1	\$ 52.00 +	
26	REAR DOOR WINDOW REGULATOR - RH <i>lit</i>	1	\$ 282.00 +	
27	REAR DOOR WINDOW REGULATOR MOTOR - RH <i>lit</i>	1	\$ 271.00 +	
28	REAR DOOR CONTROL UNIT <i>lit</i>	1	\$ 400.00 +	
29	REAR TYRE RIM - RH <i>lit</i>	1	\$ 1,262.00 +	
30	1/4 GLASS SEALANT	S/N	\$ 100.00 ✓	100
31	ACRYLIC SEALANT	S/N	\$ 180.00 ✓	180
32	CAVITY WAX	S/N	\$ 140.00 ✓	140
33	STONE CHIP TREATMENT	S/N	\$ 180.00 ✓	180
34	METAL FILLER POWDER	S/N	\$ 280.00 ✓	280
35	SUNDRIES ? nec		\$ 400.00 ?	19.20

TOTAL SPARE PARTS	:	\$ 16,313.00
TOTAL LABOUR CHARGES	:	\$ 18,732.00
GRAND TOTAL	:	\$ 35,045.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian Lij

SURVEYED DATE

:

13/10/21

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 13 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT