

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L
G S T : 5 3 3 6 0 0 6 1 L

Steel (LKK)
15/10/21, 11:30am

HL AL
5 djs
L/S

My AL sy

P-4887
-10%
4398.30

QUOTATION

N-55
L-1250 = 5703.30

QT21/YP4023C /TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

Dear Sir,
Cost of Repair to Vehicle YP4023C

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front bumper center / ON	1	1,010.00	1,010.00 ✓ P
2.	Front grille / BR	1	1,105.00	994 / 1,105.00 P
3.	Front grille clips / MC	5	6.00	15 / 30.00 nett
4.	Mit emblem / MC	1	96.00	96.00 ✓ P
5.	Fuso logo / MC	1	375.00	375.00 ✓ P
6.	Canter logo / MC (cont.)	1	75.00	75.00 ✓ P
7.	Front panel / BR / ON	1	2,436.00	2337 / 2,436.00 P
8.	Front grille garnish X AN	1	544.00	544.00 X
9.	Front number plate / BT	1	50.00	40 / 50.00 nett
10.	Labour charges	1	900.00	800 900.00 L
11.	Spray painting	1	900.00	450 900.00 L
SUB-TOTAL				S\$7,521.00

• Price exclude 7%gst

Yours faithfully,

Winnie Chai
HP: 9850-9666



LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

L/S - 4562.64
= 4550