

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

14/10/2021 11:43

JOB-NO: 50113694

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

VEHICLE DETAILS

LICENSE NO: SHA8117U TRANS: AUTO
 MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 Di
 OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD
 JOB-CODE: TP SA: Ding Auto User 2

CHASSIS: KMHC851CVLU184830
 ENGINE: G4LEKU391347

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AREA	1.00	800.00	0.00	800.00	700 /	Y	
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30 /	Y	
3 TO TRANSFER OF REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	1.00	220.00	0.00	220.00	50 /	Y	
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	260.00	0.00	260.00	30 /	Y	
5 TO RESPRAY REAR DOOR PANEL	1.00	250.00	0.00	250.00	700 /	Y	
TOTAL:		1,700.00	0.00	1,700.00			
MATERIALS							
1 REAR LH DOOR PANEL - OD	1.00	2,256.30	1789.90 /	451.26	1,805.04	L	Y
2 REAR LH DOOR FRAME UPPER BLACK TAPE - HK	1.00	9.70	/	1.94	7.76	L	Y
3 REAR LH DOOR FRAME REAR BLACK TAPE - HK	1.00	7.00	/	1.40	5.60	L	Y
4 REAR LH DOOR FRAME FRONT BLACK TAPE - HK	1.00	7.00	/	1.40	5.60	L	Y
5 REAR LH OUTER DOOR HANDLE - CH7	1.00	189.60	/	37.92	151.68	L	Y
6 REAR LH OUTER DOOR HANDLE COVER - X NN	1.00	21.10	/	4.22	16.88	L	Y
7 REAR LH OUTER DOOR HANDLE BASE - ? X NN	1.00	40.90	/	8.18	32.72	L	Y
8 REAR LH DOOR MODULE PANEL ASSY - ? X NN	1.00	350.22	/	70.04	280.18	L	Y
9 REAR LH POWER WINDOW REGULATOR MOTOR - ? X NN	1.00	785.85	/	157.17	628.68	L	Y
10 REAR LH DOOR DIVISION BAR ASSY - ? X NN	1.00	53.30	/	10.66	42.64	L	Y
11 REAR LH OUTER DOOR BELT MOULDING - ? X NN	1.00	74.90	/	14.98	59.92	L	Y
12 REAR LH DOOR LOCK - X NN	1.00	240.54	/	48.11	192.43	L	Y
13 REAR LH REAR DOOR DIVISION BAR CHANNEL RUN - ? X NN	1.00	28.00	/	5.60	22.40	L	Y
14 REAR LH DOOR GLASS RUN - ? X NN	1.00	73.10	/	14.62	58.48	L	Y
15 REAR LH OUTER DOOR HANDLE FRONT PAD - HK	1.00	5.20	/	1.04	4.16	L	Y
16 REAR LH OUTER DOOR HANDLE REAR PAD - HK	1.00	5.20	/	1.04	4.16	L	Y
17 REAR DOOR "COMFORT DELGRO" STICKER	1.00	140.00	/	0.00	140.00	S	Y
18 REAR DOOR "GOOGLE PLAY STORE" "APP STORE" STICKER	1.00	140.00	/	0.00	140.00	S	Y
19 DOOR MOULDING CLIP SET - HK	1.00	55.00	/	0.00	55.00	S	Y
20 DOOR TRIM BOARD CLIP SET - X NN	1.00	55.00	/	0.00	55.00	S	Y

2013.60
 -20%
 1610.88

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
TOTAL:		4,537.91	829.58	3,708.33			
TOTAL PARTS & LABOUR :		6,237.91	829.58	5,408.33			

EXCESS/LOADING:\$\$ 0.00

No. Of Day: 2 dys

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 14/10/91, 12.00pm

SURVEYED BY: Steve (LKK)

CONTACT NO: 14/10/91, 12.00pm

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

P - 1610.88

N - 145

L - 510

P/P - 2265.88

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: