

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0837/2021/JT
DATE : 12-Oct-21
WIP : 48369

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve,

13 days - ok - Jy - 18 Nov 21

OWNER'S NAME : MR TRIN LYOVARIN
ADDRESS : BLK 238 LORONG 1 TOA PAYOH
#09-04
SINGAPORE 310238
TELEPHONE : HP +65 91051470
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070129233
VEHICLE NO : **SJS 9687 R**
MODEL CODE : A4 2.0 TFSI S
MODEL YEAR : 12/09/2019
ENGINE NO : DEM 024293
CHASSIS NO : WAUZZZF40LN015338
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 09-Oct-21
PLACE OF ACCIDENT : CLEMENTI AVENUE 6

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJS 9687 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$ 250.00
3	TO RENEW AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELETRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	2,000.00	\$ 2,000.00
4	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	280.00	\$ 280.00
5	TO REMOVE AND REINSTALL LHS FRONT SUSPENSION ASSY WITH SUBFRAME. INSPECT FOR DAMAGED AND RENEW IF NECESSARY.	S/N \$	2,400.00	\$ 2,400.00
6	TO DISLODGE AND REINSTALL ENGINE AND GEARBOX ASSY TO FACILITATE RENEWAL OF LHS ENGINE CONSOLE AND SUPPORT.	S/N \$	1,800.00	
TOTAL LABOUR CHARGES		:	\$ 7,310.00	\$ 5,410.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJS 9687 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
		C/F		\$	5,410.00
7	TO REMOVE AND RENEW LHS AIRCOND REFRIGERANT PIPE.	S/N	\$ 280.00	\$	280.00
8	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER TOP SUPPORT AND LHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSTION RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 5,600.00	\$	2,750.00
9	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS FRONT DOOR.		\$ 4,000.00	\$	2,200.00
10	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N	\$ 520.00	\$	240.00
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N	\$ 384.00	\$	384.00
TOTAL LABOUR CHARGES		:	\$ 18,094.00	\$	11,264.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 9687 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,233.00	\$ 1,786.40
2	FRONT BUMPER FIXING PARTS	1	\$ 358.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	\$ 28.16
4	FRONT BUMPER GRILLE - CENTER	1	\$ 196.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 262.00	\$ 209.20
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 44.00	\$ 35.12
7	RADIATOR GRILLE CLOSING ELEMENT - UPPER CENTRE	1	\$ 262.00	
8	FRONT BUMPER AIR GRILLE - LH	1	\$ 135.00	\$ 108.00
9	FRONT BUMPER AIR GRILLE TRIM - LH	1	\$ 48.00	\$ 38.00
10	RADIATOR GRILLE	1	\$ 1,580.00	
11	FRONT BUMPER FOAM PIECE	1	\$ 189.00	
12	FRONT BUMPER CARRIER	1	\$ 845.00	
13	FRONT BUMPER GUIDE SECTION - LH	1	\$ 36.00	\$ 28.72
14	FRONT BUMPER TOP COVER	1	\$ 127.00	
15	CAUTION STICKER	1	\$ 14.00	
16	A/C STICKER	1	\$ 8.00	
17	LOCK CARRIER BRACKET	1	\$ 137.00	
18	FRONT BUMPER SUPPORT - LH / RH	2	\$ 58.00	
19	FRONT BUMPER RIVET	4	\$ 4.00	\$ 2.56
20	FRONT BUMPER PARKING AID SENSOR - INNER / OUTER	2	TBC	
SUB TOTAL SPARE PARTS			\$ 6,607.00	\$ 2,236.16

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 9687 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	2,236.16
21	FRONT BUMPER PARKING AID SENSOR SEAL RING	4	\$ 14.00		
22	HORN - LH	1	\$ 126.00		
23	HORN BRACKET -LH	1	\$ 29.00		
24	FRONT FENDER - LH	1	\$ 1,092.00	\$	873.60
25	FRONT FENDER ATTACHMENT PARTS	1	\$ 202.00		
26	FRONT FENDER CLOSING ELEMENT	1	\$ 72.00	\$	57.52
27	FRONT FENDER BRACKET - LH	2	\$ 67.00	\$	53.04
28	FRONT FENDER DEFORMATION BRACKET - LH	1	\$ 49.00	\$	39.20
29	FRONT FENDER BRACE - LH	1	\$ 118.00	\$	94.40
30	FRONT WHEEL HOUSING LINER - LH	1	\$ 236.00	\$	188.80
31	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 139.00		
32	FRONT WHEEL SPOILER - LH	1	\$ 73.00	\$	58.40
33	FRONT WHEEL SPOILER TRIM - LH	1	\$ 35.00	\$	27.76
34	FRONT FENDER TOP COVER - LH	1	\$ 31.00	\$	24.64
35	HEADLIGHT TOP COVER - LH	1	\$ 44.00	\$	34.48
36	FRONT FENDER LEDGE COVER - LH	1	\$ 62.00		
37	BONNET	1	\$ 3,246.00	\$	2,596.80
38	BONNET ATTACHMENT PARTS	1	\$ 412.00		
39	BONNET IMPACT PROTECTION - LH / RH / CENTER	3	\$ 84.00	\$	65.68
40	BONNET STRIKER - LH	1	\$ 50.00		
SUB TOTAL SPARE PARTS		:	\$ 6,181.00	\$	6,350.48

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 9687 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 6,350.48
41	BONNET LOCK	1 \$	214.00	
42	HEADLIGHT - LH	1 \$	7,685.00	\$ 6,148.00
43	HEADLIGHT HOSE - LH	1 \$	36.00	
44	HEADLIGHT LIFT CYLINDER - LH	1 \$	210.00	\$ 167.60
45	HEADLIGHT LIFT CYLINDER HOSE	1	TBC	
46	LOCK CARRIER	1 \$	1,016.00	\$ 812.80
47	LOCK CARRIER SUPPORT	1 \$	38.00	\$ 30.32
48	LOCK CARRIER BRACKET	1 \$	19.00	
49	INTERCOOLER	1 \$	587.00	\$ 469.20
50	A/C PRESSUPRE PIPE - LH	1 \$	427.00	
51	A/C REFRIGERANT LINE	3 \$	755.00	\$ 133.20
52	A/C CONDENSER	1 \$	622.00	
53	A/C REFRIGERANT PIPE	1 \$	523.00	\$ 418.00
54	A/C REFRIGERANT PIPE BRACKET	1 \$	8.00	\$ 5.76
55	RADIATOR	1 \$	904.00	\$ 722.80
56	RADIATOR FAN RING	1 \$	267.00	
57	COOLANT	6 \$	266.00	
58	RADIATOR AIR GUIDE - LH / LH OUTER / LOWER	2 \$	82.00	\$ 52.32
59	NOISE INSULATION	1 \$	572.00	\$ 457.60
60	FRONT TYRE RIM - LH	1 \$	1,155.00	
SUB TOTAL SPARE PARTS		:	\$ 15,386.00	\$ 15,768.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 9687 R

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	15,768.08
61	FRONT SUB FRAME	1	\$ 1,891.00	\$	1,512.80
62	FRONT SUB FRAME SUPPORT BRACKET - LH	1	\$ 472.00	\$	377.60
63	DRIVE SHAF HEAT SHEILF - LH	1	\$ 32.00		
64	GEARBOX MOUNTING	1	\$ 212.00		
65	GEARBOX SUPPORT	1	\$ 82.00		
66	ENGINE MOUNTING	1	\$ 422.00		
67	ENGINE MOUNTING SUPPORT - LH	1	\$ 158.00		
68	ENGINE SUPPORT BEARING - LH	1	\$ 67.00		
69	FRONT WISHBONE LINK - LH	1	\$ 539.00		
70	FRONT SUSPENSION GUIDE - LH FRONT	1	\$ 943.00		
71	FRONT CONTROL ARM - LH UPPER FRONT	1	\$ 512.00		
72	FRONT CONTROL ARM - LH UPPER REAR	1	\$ 512.00		
73	FRONT WHEEL BEARING HOUSING - LH	1	\$ 968.00		
74	SWIVEL JOINT	1	\$ 193.00		
75	FRONT WHEEL HUB - LH	1	\$ 479.00		
76	FRONT WHEEL BEARING - LH	1	\$ 246.00		
77	FRONT SUSPENSION FORKS - LH	1	\$ 264.00		
78	FRONT COUPLING ROD - LH	1	\$ 127.00		
79	ANTI-ROLL BAR	1	\$ 433.00	\$	346.00
80	FRONT ABSORBER - LH	1	\$ 301.00		
SUB TOTAL SPARE PARTS		:	\$ 8,853.00	\$	18,004.48

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 9687 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 18,004.48
81	DRIVE SHAFT - LH	1	\$ 2,650.00	
82	STEERING SHAFT	1	\$ 6,787.00	
83	TIE ROAD END	1	\$ 197.00	
84	TRACK ROD	1	\$ 99.00	
85	FRONT NO. PALTE	S/N	\$ 60.00	
86	SUNDRIES		\$ 500.00	\$ 183.36
TOTAL SPARE PARTS		:	\$ 47,320.00	\$ 18,187.84
TOTAL LABOUR CHARGES		:	\$ 18,094.00	\$ 11,264.00
GRAND TOTAL		:	\$ 65,414.00	\$ 29,451.84

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-15/11/21