

Our Job Ref No :

305489644

Date

09/10/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Luyang Drive, Singapore 508669
Fax: 6348 8198

FINALIZATION FORM

To :

LKK

Attn :

THEVAN

Fax :

Vehicle Reg No. :

SHD6521H

06/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2 The repair job shall bill to:

NTUC

SMH2631U

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$361.00

(b) Labour Charges

\$ 660.00

Total for Part-By-Part Repair Cost

\$ 1,021.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs:

2

working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature :

Name : Thevan

Date : 20/10/21

10

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO SHD6521H ✓

MAKE 23.01.2020

MODEL IONIQ G3

06/10/21

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40 <i>Kr</i>
1	REAR BUMPER SIDE BRACKET LH/RH		\$111.60 \$55.80 <i>SVC</i>
10	REAR BUMPER CLIPS		\$2.20 \$22.00 <i>SVC</i>
1	REAR BUMPER CENTRE MOULDING		\$451.25 <i>SVC</i>
1	REAR BUMPER REFLECTOR RH		\$41.45 <i>SVC</i>
	SUB TOTAL		\$1,029.90
	20.00%		\$205.98
	DISCOUNTED TOTAL		\$823.92
1	REAR BUMPER MAT		\$50.00 <i>SVC</i>
1	REAR REVERSE SENSOR		\$180.00 <i>SVC</i>
			\$230.00
	Labour Charge		
	Panel Beating		\$450.00 <i>350</i>
	Spray Painting Charge		\$300.00 <i>250</i>
	Check Wiring and Lighting		\$60.00 <i>30</i>
	Remove/refix Reverse sensor		\$60.00 <i>30</i>
	TOTAL LABOUR		\$870.00
	ESTIMATE TOTAL		\$1,923.92
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

thuan@lkhau to .com

8223 5769

7/10/21 1615

P/P bfr paint photo

2 day wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305489644
REGN NO : SHD6521H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 23.01.2020
DATE/TIME IN : 06.10.2021 13:50
ACCIDENT DATE : 06.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2533-G MOULDING ASSY-RR BUMPER C 1 451.25 20.00 361.00

SUB-TOTAL : 361.00

JOB NATURE

0000 SP SPRAYPAINT CHARGE 250.00

0001 17-01 CHECK ALL LIGHTING 30.00

0002 20-22 REMOVE/REFIX REVERSE SENSOR 30.00

0003 PB PANEL BEATING - SHD6521H 350.00

SUB-TOTAL : 660.00

TOTAL : 1,021.00

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO