

KIRALY MOTORS PTE LTD

8, KAKI BUKIT AVE 4 , #06-43,S(415875)

Tel : 85498387

Email: tfyong1966@gmail.com

Reg : 201439365W

Vehicle Number : SMT 95 S
Vehicle Model : MER. BENZ E200 CGI A
Accident Date : 11.10.2021
Original Reg Date : 09.12.2010

Date : 14.10.2021
Chassis : WDD2074482F060758
TP Ins. CHINA
TAIPING

Asher.

ESTIMATE

1	1 pc	Bonnet			1,485.60
2	1 pc	Bonnet Badge			98.70
3	1 pc	Front Grille			1,158.90
4	1 pc	Front Grille LOGO			154.90
5	1 pc	Front support top garnish			258.70
6	1 pc	Front Grille inner suport bar LH			187.60
7	1 set	Front Grille Clips			30.00
8	2 pc	Headlamps	2,650.80		5,301.60
9	2 pcs	Headlamp Bottom brackets	145.90		291.80
10	1 pc	Front Bumper			1,785.60
11	1 pcs	Front Bumper Side Retainers			158.30
12	2 pcs	Front bumper centre inner brackets	98.70		197.40
13	1 set	Front Bumper Clips			50.00
14	1 pc	Front Bumper towing cover			78.20
15	2 pc	Front Bumper headlamp nozzle covers	85.60		171.20
16	4 pc	Front Bumper sensors	268.90		537.80
17	4 pc	Front Bumper sensors holders	68.50		137.00
18	1 pc	Front Bumper lower grille			248.60
19	1 pc	Front Bumper lower grille bracket			198.50
20	2 pc	Front Bumper foglamp covers	98.70		197.40
21	2 pc	Front Bumper foglamp	308.90		617.80
22	1 pc	Front Bumper Sponge			208.50

13,554.10

Less 10% 1,355.41

12,198.69

5419.40

4877.46

Special Nett

1	1 pc	Front Number Plate (customized) <i>xle m</i>		120.00	<i>+</i>
2	1 pc	Front bumper lower lip <i>3 m</i>		850.00	<i>+</i>
3	1 pc	Front bumper centre lower lip garnish <i>3 m</i>		450.00	<i>+</i>

Labour charge

Panel Beating		1,800.00	<i>300</i>
Spray painting		1,800.00	<i>250</i>
Check Wiring on headlamp		120.00	<i>30</i>
Anti rust		160.00	<i>580</i>

\$ 17,498.69

Admin Cj

h/s 14/10/21.

03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5457.46

h/s: 4.31c.