

# Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

( Email Adress : woonmeng @singnet.com.sg )

Co Reg No. 200603678M

GST Reg No. 20-0603678M

## Estimate

## TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd  
Motor Claims Dept

Date : 15 Oct 2021

Dear Sirs :

Fax : 6224 1047

**RE : ESTIMATE COST FOR SEAT ARONA 1.0 - SNB3098Y**

**ACCIDENT INVOLVING SNB3098Y, SJA3742Z & OTHERS ON 14/10/2021**

| <u>ITEMS</u>               | <u>DESCRIPTION</u>               | <u>QTY</u> | <u>PRICE</u>        |
|----------------------------|----------------------------------|------------|---------------------|
| 1                          | Rear bootlid                     | 1pc        | \$ bt / 2,120.00    |
| 2                          | Rear bootlid hinge @\$           | 1pc        | \$ Rr 165.00        |
| 3                          | Rear bootlid lock                | 1pc        | \$ bt / 185.00      |
| 4                          | Rear bootlid inner trim          | 1pc        | \$ x n / 330.00     |
| 5                          | Rear bumper                      | 1pc        | \$ de / 1,380.00    |
| 6                          | Rear bumper retainer @\$65ea     | 2pcs       | \$ R n / 130.00     |
| 7                          | Rear bumper center top garnish   | 1pc        | \$ de / 550.00      |
| 8                          | Rear bumper center lower garnish | 1pc        | \$ de / 990.00      |
| 9                          | Emblem                           | 1pc        | \$ ne / 115.00      |
| 10                         | ARONA                            | 1pc        | \$ ne / 98.00       |
| 11                         | FR                               | 1pc        | \$ ne / 70.00       |
| 12                         | Rear bumper sponge               | 1pc        | \$ de / 95.00       |
| 13                         | Rear bumper reinforcement        | 1pc        | \$ bt / 540.00      |
| 14                         | Rear end panel                   | 1pc        | \$ Rr 500.00        |
| 15                         | Rear sensor @300ea 2ea           | 2pcs       | \$ n / 600.00 400 . |
| <b>Sum Carried Forward</b> |                                  |            | <b>\$ 7,868.00</b>  |

6543

**Sum Carried Forward****\$ 7,868.00**

- 16 Rear windscreen sealant  
17 Rear number plate

2pcs \$ 40.00 *neu*  
1pc \$ 35.00 *xxx CRA ✓*  
\$ 7,943.00 *75*

**Labour Charge & Misc**

To remove, replace, repair & weld rear damaged parts. } \$ 850.00 *600.*  
To remove & replace rear windscreen glass \$ 150.00 *120*  
To R & R light wiring. \$ 60.00 *30*  
To anti rust \$ 80.00 *30*  
To R & R upholster \$ 120.00 *80*  
To R & R sensor wiring \$ 60.00 *30*  
To R & R camera wiring \$ 60.00 *30*  
To putty & spray painting \$ 1,000.00 *700*  
**Total** \$ 10,323.00 *1620*

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

*Tanfer 97495749*  
*WP 15/10/21 12pm*  
*P/P Resurvey before part.*  
*6 days*  
*Tanfer C/Unsub. com*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

( Email Address : woonmeng @singnet.com.sg )

Co Reg No. 200603678M

GST Reg No. 20-0603678M

## Estimate

## TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd  
Motor Claims Dept

Date : 15 Oct 2021

Dear Sirs :

Fax : 6224 1047

### RE : ESTIMATE COST FOR SEAT ARONA 1.0 - SNB3098Y ( SUPPLEMENTARY ACCIDENT INVOLVING SNB3098Y, SJA3742Z & OTHERS ON 14/10/2021

| <u>ITEMS</u> | <u>DESCRIPTION</u>              | <u>QTY</u> | <u>PRICE</u>           |
|--------------|---------------------------------|------------|------------------------|
| 1            | Rear safety belt @\$940ea       | 2pcs       | \$ 1,880.00 <i>act</i> |
| 2            | Front safety belt @\$750ea      | 2pcs       | \$ 1,500.00 <i>act</i> |
| 3            | Rear pillar inner trim @\$170ea | 2pcs       | \$ 340.00 <i>de</i>    |
|              |                                 |            | <b>\$ 3,720.00</b>     |

### Labour Charge & Misc

To perform diagnostics

\$ 250.00 *180 net*

**Total**

**\$ 3,970.00**

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

*Parts - 6543  
3720  
10263  
10% - 9236.70  
SN XXX 75  
1620  
180*

~~XXXXXXXXXXXX~~ \$11,111.70

*06 days  
X*