

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

14-Oct-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6355 B ✓

1 pc	Front bumper	\$	531.00	Xr
1 pc	Front bumper emblem	\$	44.00	Xr
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$	32.00	7. Xsuc
1 pc	Front bumper n/s upper bracket	\$	16.00	7. Xsuc
1 pc	Front bumper n/s support bracket	\$	16.00	7. Xsuc
1 pc	Front bumper n/s protector	\$	51.00	Xsuc
1 pc	Front n/s wheel cover	\$	116.00	Xwnc
1 pc	Front n/s fender	\$	384.00	Xr
1 pc	Front n/s fender inner shield	\$	120.00	Xsuc
		\$	1,310.00	
		Less 10%	\$	337.90
			\$	972.10

S/NETT

1 set	Front bumper clips	\$	48.00	✓ nec
1 pc	Front n/s fender sticker	\$	30.00	✓ nec
1 set	Front n/s fender inner shield clips	\$	28.00	✓ nec
Sundry		\$	50.00	Xsuc
To focus and adjust front n/s & o/s head lamps		\$	60.00	30
To check front wheel alignment		\$	80.00	XNN
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	600.00	360
To putty and spray painting on front bumper, front n/s fender, front door LH, side mirror LH		\$	600.00	360
To apply rustproofing on the repaired and replaced panels.		\$	60.00	30
		\$	2,528.10	✓

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To inspect damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Therian@LKKAuto.com
82235769
19/10/21 1500
L/S after repair photo
Labour only

2 day swp
F: \$886