



No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SML3668L

Type of Claim : TP

Vehicle No. : SML3668L

Make & Model : BLUECAR

Year of Manufacture : 2018

Chassis No. : VL4BCEB4RJT003539

Ins Company : AIG ASIA PACIFIC
INSURANCE

Engine No. :

Excess :

Policy No. : SD21V00611/VPZ/R01

Date of Accident : 02/10/2021

Time of Accident : 00:00:00

Suggested Days of Repair : 8

Case Owner : BLUECAR EAST ASIA PTE LTD

TP Vehicle No. : SJV7727G

Repair Estimates

Parts (a) Cost / List Price Items \$ 8,987.00

Plus/Less- 20.0% \$ 1,797.40

Total of Cost / List \$ 10,784.40

(b) Nett Price Items \$ -

Less \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 120.00

Total Parts Cost (Appendix A) \$ 10,904.40

Labour (Appendix B) \$ 3,620.00

Total Repair Cost \$ 14,524.40

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Taufik 1745749

Company : LKK.

Survey conducted on : 15/10/21 at 6615


Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 8 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : 

Date: 15/10/21

Resurvey before / after report.



VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

FINALIZATION REPAIR COST DETAILS

Vehicle No : SML3668L Case Owner : BLUECAR EAST ASIA PTE LTD

Make & Model : BLUECAR Year Manufacture : 2018

Chassis No : VL4BCEB4RJT003539 Engine No : 0

Date & Time : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	FRONT BUMPER <i>de</i>	1	\$ 1,493.00	\$ 1,493.00			
2	FRONT BUMPER CLIPS <i>na</i>	10	\$ 1.00	\$ 10.00			
3	FRONT REINFORCEMENT ?	1	\$ 240.00	\$ 240.00			
4	FRONT REINFORCEMENT BRACKET ?	2	\$ 200.00	\$ 400.00			
5	FRONT BUMPER SPONGE WITH CLIPS <i>cha</i>	1	\$ 169.00	\$ 169.00			
6	FRONT SUPPORT PANEL <i>bt</i>	1	\$ 412.00	\$ 412.00			
7	FRONT BONNET LOCK ?	1	\$ 96.00	\$ 96.00			
8	FRONT BONNET <i>bt</i>	1	\$ 1,197.00	\$ 1,197.00			
9	BONNET HINGE LH <i>Ry</i>	1	\$ 125.00	\$ 125.00			
10	BONNET HINGE RH <i>Ry</i>	1	\$ 125.00	\$ 125.00			
11	BONNET STICKER <i>na</i>	1					\$ 30.00
12	FRONT RADIATOR AIR GUIDE <i>de</i>	1	\$ 62.00	\$ 62.00			
13	AIR GUIDE CLIP <i>na</i>	7	\$ 1.00	\$ 7.00			
14	AIRCON CONDENSER ?	1	\$ 527.00	\$ 527.00			
15	RADIATOR ?	1	\$ 530.00	\$ 530.00			
16	RADIATOR FAN MOTOR WITH COWLING ?	1	\$ 606.00	\$ 606.00			
17	HEADLAMP FRAME RH <i>na</i>	1	\$ 134.00	\$ 134.00			
18	HEADLAMP FRAME LH <i>na</i>	1	\$ 137.00	\$ 137.00			
19	REAR BUMPER <i>de</i>	1	\$ 1,405.00	\$ 1,405.00			
20	REAR BUMPER REINFORCEMENT ?	1	\$ 82.00	\$ 82.00			
21	REAR BUMPER REINFORCEMENT BRACKET LH ?	1	\$ 43.00	\$ 43.00			
22	REAR BUMPER REINFORCEMENT BRACKET RH ?	1	\$ 43.00	\$ 43.00			
23	REAR BUMPER REFLECTOR RH <i>X</i>	1	\$ 126.00	\$ 126.00			
24	REAR BUMPER REFLECTOR LH <i>na</i>	1	\$ 125.00	\$ 125.00			
25	REAR END PANEL <i>Ry</i>	1	\$ 450.00	\$ 450.00			
26	CHARGER AIR INLET ?	1	\$ 115.00	\$ 115.00			
27	CHARGER AIR INLET GASKET ?	1	\$ 6.00	\$ 6.00			
28	REAR AIR VENT (BOOT/TRUNK) ?	2	\$ 46.00	\$ 92.00			
29	REAR NUMBER PLATE LAMP ?	2	\$ 115.00	\$ 230.00			
30	NUMBER PLATE WITH CASING <i>na</i>	2					\$ 90.00

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 8,611.00 \$ 8,987.00 \$ - \$ - \$120.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR
EAST ASIA

Case Owner
Year of Manufacture

: PTE LTD

: 2018

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.