

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0851/2021/TF
DATE : 15-Oct-21
WIP : 49125

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY

YOUR INSURED VEH NO : SBX 8668 X

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 04 Jan 22

OWNER'S NAME : MS FENG XIMEI
ADDRESS : 6 PETIR ROAD
#08-02
SINGAPORE 678267
TELEPHONE : HP +65 9270 8959
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210103863
VEHICLE NO : **SNB 5773 T**
MODEL CODE : AUDI A5 2.0 SPORTBACK 2.0 TFSI
MODEL YEAR : 30/08/2021
ENGINE NO : DEM 032946
CHASSIS NO : WAUZZZF57MA054431
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Oct-21
PLACE OF ACCIDENT : CAR PARK AT SINGPOST, BUKIT PANJANG

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 5773 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHTS. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,672.00	\$ 2,272.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 5773 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,342.00	
2	FRONT BUMPER SECURING STRIP	2	\$ 71.00	
3	FRONT BUMPER GRILLE - CENTRE	1	\$ 196.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 262.00	
5	FRONT BUMPER AIR GUIDE - LH	1	\$ 63.00	
6	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 262.00	
7	FRONT BUMPER AIR GRILLE - LH	1	\$ 135.00	
8	FRONT BUMPER AIR GRILLE COVER - LH	1	\$ 48.00	
9	FRONT BUMPER LOWER TRIM - CENTER	1	\$ 114.00	
10	RADIATOR GRILLE	1	\$ 1,694.00	
11	FRONT BUMPER FOAM PIECE	1	\$ 146.00	
12	FRONT BUMPER CARRIER	1	\$ 845.00	
13	FRONT BUMPER TOP COVER	1	\$ 127.00	
14	CAUTION STICKER	1	\$ 14.00	
15	A/C STICKER	1	\$ 8.00	
16	LOCK CARRIER BRACKET	1	\$ 137.00	
17	FRONT BUMPER SUPPORT - LH / RH	2	\$ 58.00	
18	RIVET	4	\$ 4.00	
19	FRONT BUMPER PARKING AID SENSOR	2	TBC	
20	FRONT BUMPER PARKING AID SENSOR SEAL RING	4	\$ 14.00	
SUB TOTAL SPARE PARTS		:	\$ 6,540.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 5773 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN - LH	1	\$ 126.00	
22	HORN BRACKET - LH	1	\$ 29.00	
23	HEADLIGHT - LH	1	\$ 7,685.00	
24	HEADLIGHT LIFT CYLINDER - LH	1	\$ 198.00	
25	HEADLIGHT LIFT CYLINDER HOSE	1	TBC	
26	RADIATOR AIR GUIDE - LH / LOWER LH / UPPER	3	\$ 64.00	
27	FRONT NO. PLATE	S/N	\$ 60.00	
28	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 15,002.00	\$..
TOTAL LABOUR CHARGES		:	\$ 4,672.00	\$ 2,272.00
GRAND TOTAL		:	\$ 19,674.00	\$ 2,272.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.