

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0851/2021/TF  
**DATE** : 15-Oct-21  
**WIP** : 49125

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY**

**YOUR INSURED VEH NO : SBX 8668 X**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MS FENG XIMEI  
**ADDRESS** : 6 PETIR ROAD  
#08-02  
SINGAPORE 678267  
**TELEPHONE** : HP +65 9270 8959  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 7210103863  
**VEHICLE NO** : **SNB 5773 T**  
**MODEL CODE** : AUDI A5 2.0 SPORTBACK 2.0 TFSI  
**MODEL YEAR** : 30/8/2021  
**ENGINE NO** : DEM 032946  
**CHASSIS NO** : WAUZZZF57MA054431  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 14-Oct-21  
**PLACE OF ACCIDENT** : CAR PARK AT SINGPOST, BUKIT PANJANG

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 5773 T

| S/N                         | NATURE OF JOBS                                                                                                                                          |        | ESTIMATED<br>CHARGES |                        |
|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|------------------------|
| 1                           | TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS<br>FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE<br>SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING<br>AID    | S/N \$ | 480.00               | ✓                      |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL<br>UNIT AND POWER MODULE.                                                                                | S/N \$ | 400.00               | X                      |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER AND LHS<br>HEADLIGHTS. TO REPAIR BONNET. RE-ORGANIZE CRASH<br>MANAGEMENT COMPONENTS. REINSTALL ALL PARTS<br>REMOVED | \$     | <del>1,600.00</del>  | 500                    |
| 4                           | TO RESPRAY FRONT BUMPER AND BONNET.                                                                                                                     | \$     | <del>2,000.00</del>  | 1100                   |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                          | S/N \$ | 192.00               | ✓                      |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                         | :      | <u>\$</u>            | <u><b>4,672.00</b></u> |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 5773 T**

|                              |                                                         |     | DAMAGED PARTS & PRICES |         |
|------------------------------|---------------------------------------------------------|-----|------------------------|---------|
| S/N                          | PARTS DESCRIPTION                                       | QTY | S/NETT                 | REMARKS |
| 1                            | FRONT BUMPER <i>Repair</i>                              | 1   | \$ 2,342.00            | +       |
| 2                            | FRONT BUMPER SUCURING STRIP                             | 2   | \$ 71.00               | +       |
| 3                            | FRONT BUMPER GRILLE - CENTRE <i>from</i>                | 1   | \$ 196.00              | +       |
| 4                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>from</i> | 1   | \$ 262.00              | +       |
| 5                            | FRONT BUMPER AIR GUIDE - LH                             | 1   | \$ 63.00               | +       |
| 6                            | RADAIOR GRILLE CLOSING ELEMENT                          | 1   | \$ 262.00              | +       |
| 7                            | FRONT BUMPER AIR GRILLE - LH <i>from</i>                | 1   | \$ 135.00              | +       |
| 8                            | FRONT BUMPER AIR GRILLE COVER - LH                      | 1   | \$ 48.00               | +       |
| 9                            | FRONT BUMPER LOWE TRIM - CENTER                         | 1   | \$ 114.00              | +       |
| 10                           | RADIATOR GRILLE                                         | 1   | \$ 1,694.00            |         |
| 11                           | FRONT BUMPER FOAM PIECE <i>from</i>                     | 1   | \$ 146.00              | +       |
| 12                           | FRONT BUMPER CARRIER                                    | 1   | \$ 845.00              | +       |
| 13                           | FRONT BUMPER TOP COVER                                  | 1   | \$ 127.00              | +       |
| 14                           | CAUTION STICKER <i>from</i>                             | 1   | \$ 14.00               | +       |
| 15                           | A/C STICKER                                             | 1   | \$ 8.00                | +       |
| 16                           | LOCK CARRIER BRACKET                                    | 1   | \$ 137.00              | +       |
| 17                           | FRONT BUMPER SUPPORT - LH / RH <i>from</i>              | 2   | \$ 58.00               | +       |
| 18                           | RIVET                                                   | 4   | \$ 4.00                | +       |
| 19                           | FRONT BUMPER PARKING AID SENSOR                         | 2   | TBC                    |         |
| 20                           | FRONT BUMPER PARKING AID SENSOR SEAL RING <i>from</i>   | 4   | \$ 14.00               | +       |
| <b>SUB TOTAL SPARE PARTS</b> |                                                         |     | <b>\$ 6,540.00</b>     |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 5773 T**

|                             |                                            |     | DAMAGED PARTS & PRICES |         |
|-----------------------------|--------------------------------------------|-----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION                          | QTY | S/NETT                 | REMARKS |
| 21                          | HORN - LH                                  | 1   | \$ 126.00              | ✓       |
| 22                          | HORN BRACKET - LH                          | 1   | \$ 29.00               | ✓       |
| 23                          | HEADLIGHT - LH                             | 1   | \$ 7,685.00            | ✓       |
| 24                          | HEADLIGHT LIFT CYLINDER - LH               | 1   | \$ 198.00              | ✓       |
| 25                          | HEADLIGHT LIFT CYLINDER HOSE               | 1   | TBC                    |         |
| 26                          | RADIATOR AIR GUIDE - LH / LOWER LH / UPPER | 3   | \$ 64.00               | ✓       |
| 27                          | FRONT NO. PLATE                            | S/N | \$ 60.00               | ✓       |
| 28                          | SUNDRIES                                   |     | \$ 300.00              | ✓       |
| <b>TOTAL SPARE PARTS</b>    |                                            | :   | <b>\$ 15,002.00</b>    |         |
| <b>TOTAL LABOUR CHARGES</b> |                                            | :   | <b>\$ 4,672.00</b>     |         |
| <b>GRAND TOTAL</b>          |                                            | :   | <b>\$ 19,674.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



**PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*  
SURVEYED DATE : *20/10/21*  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : *not authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT