

Our Job Ref No 305489201

Date : 05/10/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6548 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

: SH 9637L

DOA: 01/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SJU7741U

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

\$1,350.00

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : 

Name : THEVAN

Date : 15/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTMC (Upsum)

Tu

Date: 04.10.2021

Time: 09:23:47

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305489201
REGN NO : SH 9637L ✓
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 15.08.2018
DATE/TIME IN : 02.10.2021 11:35
ACCIDENT DATE : 01.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	Xr ✓ Det
0002 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	✓ Cut
0003 04-01-0104-2544-G	CAP-RR HOOK	1	98.80	20.00	79.04	✓ Scr
0004 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	X/c ✓ nec
0005 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	✓ Jnlc
0006 04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00	315.84	X suc
0007 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	10.00	162.00	✓ Cut
0008 28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1	50.00	1.00-	50.00	✓ 169

SUB-TOTAL : 1,403.00

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 04.10.2021

Time: 09:23:47

Page: 2

JG

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305489201
REGN NO : SH 9637L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 15.08.2018
DATE/TIME IN : 02.10.2021 11:
ACCIDENT DATE : 01.10.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 780.00

TOTAL : 2,183.00

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Thavan@Lkhauto.com
82235769

4/10/21 1700

L/S after repair photo

wp 2days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
CHECK ITEM			
REAR BUMPER ASSY		\$459.40	LIST
REAR BUMPER MAT		\$50.00	NET
LABOUR			
TOTAL:		\$509.40	JUMANI