TP A16.

## **MCS** Garage

10 Kaki Bukit Road 2 #03-25, First East Centre Singapore 471868 Tel: 9270 0917 / 6538 4322

Vehicle number: <u>SJS4178B</u> Vehicle Made & Model: <u>TOYOTA ALTIS</u>

Qty	List Items	Amount \$
1	Rear bumper Distorted	561.90
2	Rear bumper reflectors - L/R @ 41.50 Cruded	83.00
1	Rear bumper foam Creek	180.93
2	Rear bumper brackets - L/R @ 110.25 LH Dund	220.50-110.25.
2	Rear bumper side retainers - L/R @ 91.50	183.00 90
2	Rear bumper side brackets - L/R @ 89.95 x+e m	179.90
1	Rear boot lid Pers	861.90
1	Rear boot logo	68.60 ✓
1	Rear boot emblem "1.6"	52.40
1	Rear boot emblem "COROLLA"	68.20
1	Rear boot emblem "ALTIS"	68.20
2	Rear boot lamps - L/R @ 211.50 MM M	423.00 🗡
1	Rear boot inner lock 7	260.95⊁
1	Rear boot lock sticker	78.85
1	Rear boot w/strip	169.43
1	Rear end panel Dented	780.65
1	Rear end panel garnish nn	160.93
1	Rear floor board	380.60
2	Rear taillamps - L/R @ 411.50 💢	823.00 GXO.
2	Rear taillamp lower brackets @ 86.55 7	173.10 🗸
2	Rear taillamp panels - L/R @ 211.50	423.00
	Sub-total	6,202.04
	Less 25%	1,550.51
	Total List	4,651.53
		271413
		2714.13

Vehicle Made & Model: TOYOTA ALTIS Vehicle number: SJS4178B Special Nett Items 45.00-30 230. 1 set Rear bumper clip Nec 280.00 200 1 set Rear reverse sensor Danyed 325.00 **Total Special Nett** Labour charges 50.00 30. To check rear electrical wiring 120.00 60. To remove, refix rear interior trims to assist repair 80.00 50 To remove, refix rear reverse sensor 120.00 60 To respray undercoating 1,200.00 800 To respray painting and etc 1,200.00 600. Panel beating, cut, weld remove & replacing above parts 2,770.00 **Total Labour** 

## **ESTIMATE PARTS AND LABOUR GRAND TOTAL \$**

7,746.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 386505. NS: 3.1KV