

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21010619/UUY3E2

Date: 22/10/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00025112100

Claimant Vehicle No : FBP4225J

Insured Vehicle No : GBG6849T

Date of Loss: 06/10/2021

Nature of Claim: TP

Claim No: SNM21D205793/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP4225J**

Make & Model: YAMAHA MT-03 ABS (MTN320-A), 321cc

Engine No: H405E0020760

Reg. Date: 29/03/2019 (Man. Year: 2019)

Chassis No: MH3RH125000010437

Colour: Black

Odometer: 0 km

Engine Capacity: 321 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17

Rear Tyre Size: 160/60Z R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/10/2021

Date Inspected: 15/10/2021 Inspected At:

Sanfu Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6, #02-43 Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 0.0 days

Adjuster: MARCUS CHUA

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$13,000.00
OMV :	\$4,825.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$3,469.00
COE Rebate (2) :	\$2,584.00
Total Rebate (1) + (2) = :	\$2,584.00

The total amount incurred will be Market Value \$13,000 minus Total Rebate \$2,584 = \$10,416 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Oct 2021)	
Parts:	N/A	YAMAHA MT-03 ABS (MTN320-A) 321cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP4225J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >