

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD78K**

AAD2110-

*Not Authored  
11 Sep & 2020*

Vehicle No.:  
Chassis No.:  
Vehicle Make: **14 OCT 2021**  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

**SHD78K**  
VF1ABL15AUC283326  
RENAULT  
LATITUDE  
13/10/2021  
**TOKIO**  
31/08/2016

PART	LIST
1 BUMPER COVER FRT	\$ Bu 747.20 ✓
1 BUMPER ABSORBER FRT	\$ In 394.68 X
1 BUMPER BEAM FRT	\$ N 663.70 X
1 BUMPER BRACKET KIT FRT RH	\$ Dr 101.40 ✓
1 HEADLAMP RH	\$ My car 743.60 ✓
1 WIPER RESERVOIR	\$ Bu 179.60 X
1 FENDER PANEL FRT RH	\$ Bu 437.10 ✓
1 WHEELARCH FRT RH	\$ In 191.40 X
	<b>\$ 3,267.28</b>
	10% \$ <b>326.73</b>
	<b>\$ 2,940.55</b>

Special Nett	
1SET BUMPER BRACKET CTR CLIP	\$ na na 33.00 X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$ na 10.00 X
1SET BUMPER RETAINER RH CLIP RR	\$ na 20.00 X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$ na 10.00 X
1SET BUMPER RETAINER CLIP LH RR	\$ na 20.00 X
1 BUMPER CLIP FRT	\$ nke 85.00 <del>65.00</del>
1 FENDER CLIP	\$ in 65.00 X
1 FENDER LINER CLIP	\$ na 60.00 X
<b>TOTAL</b>	<b>\$ 303.00</b>
<b>TOTAL PARTS</b>	<b>\$ 3,243.55</b>

**LABOUR**

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *440*

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD78K**

**AAD2110-**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	4000
To Rust-Proofing Of The Affected Areas.	\$	170.00	300
To reinstall rear bumper parking sensor.	\$	na 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	200

**TOTAL \$ 7,580.00**

**Over All Total \$ 13,764.10**

**(LUMP SUM)**

**Repair Days**

**10 DAYS**

**2 days**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey - s on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: