



FALCON - AIR AUTO SERVICES PTE LTD

Co Reg No : 199501140D
GST Reg No : 199501140D

Page 1 / 2

FALCON - AIR

AIILENA SHANTHI D/O B NARAYAN DAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
ADRIAN GAN - 96916071

Estimate : ES012271

Attention : Motor Claim Department

Date : 15/10/2021
Vehicle Num. : SLT 5674A
Make/Model : HYUNDAI ELANTRA AD GLS-2017
Chassis/Eng# : KMHD841CMJU570014
Accident Date : 14/10/2021
Claim No. :
Reference : TP - NTUC AGT BUDGET DIRECT
Policy No. : 5095989571-03*Not Notified*
11/2/21 \$4450/1
6 days

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	LH REAR DOOR		1715
2.	2 PCS	LH REAR DOOR BLACK TAPE		
3.	1 PC	LH REAR DOOR WEATHERSTRIP		
4.	1 PC	LH REAR DOOR INNER LOCK		
5.	1 PC	LH REAR DOOR GLASS REGULATOR		
6.	1 PC	LH REAR DOOR GLASS REGULATOR MOTOR		
7.	1 PC	LH REAR DOOR TRIM BOARD		
8.	1 PC	LH REAR DOOR LOWER STICKER		
9.	1 PC	LH ROCKER PANEL STICKER		
10.	1 PC	LH REAR FENDER		1768.30
11.	1 PC	LH REAR SPORTS RIM		671.30
List Total S\$:				5,789.10
20.00% Discount S\$:				1,157.82
				4,631.28
LABOUR :				
TO REMOVE/REFIX REAR WINDSCREEN GLASS				120.00
TO CONDUCT WATER TEST TO CHECK FOR LEAKAGE				50.00
TO TRANSFER LH REAR DOOR MECHANISM				100.00
TO REMOVE/REFIX TRIMS, SPEAKERBOARD, SEATS, ETC				

B1	1,878.30	✓
15.00	30.00	✓
Sm	85.10	X
R	191.50	X
Sm	223.40	X
Sm	160.50	X
Sm	597.00	X
Sm	30.00	✓
Sm	30.00	✓
B1	1,892.00	✓
Sm	671.30	✓

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



FALCON-AIR

AIILENA SHANTHI D/O B NARAYAN DAS
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721
ADRIAN GAN - 96916071

Attention: Motor Claim Department

Estimate: ES012271

Date: 15/10/2021
Vehicle Num.: SLT 5674A
Make/Model: HYUNDAI ELANTRA AD GLS-2017
Chassis/Eng#: KMHD841CMJU570014
Accident Date: 14/10/2021
Claim No.:
Reference: TP - NTUC AGT BUDGET DIRECT
Policy No.: 5095989571-03

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO FACILITATE REPAIRS		280.00 <i>12d</i>
		TO REMOVE/REFIX FUEL TANK TO ASSIST REPAIR		180.00 <i>60d</i>
		TO CONDUCT WHEEL ALIGNMENT (COMPUTERISE)		120.00 <i>60d</i>
		TO TRANSFER NEW RIM TO TYRE AND BALANCING		50.00 <i>20d</i>
		TO RUSTPROOF ACCIDENT DAMAGE AREA		200.00 <i>60d</i>
		TO STRAIGHTEN LH FRONT DOOR, LH REAR FENDER, LH ROCKER		
		PANEL, INNER PANEL, CUT OUT/RE-WELD LH REAR FENDER		<i>800d</i>
		INCLUDING REPLACEMENT OF PARTS		1,500.00 <i>800d</i>
		TO SPRAY PAINT ON LH REAR FENDER, OUTER/INNER, LH ROCKER		
		PANEL, LH REAR DOOR, LH FRONT DOOR		1,300.00 <i>60d</i>
		Labour Total S\$:		3,900.00

E. & O.E.

Total S\$: 8,531.28

=====

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.