



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 5674A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LH REAR DOOR	BENT	1,878.30	1,775.00
2	LH REAR DOOR BLACK TAPE @\$15.00	NECESSARY	30.00	30.00
1	LH REAR DOOR WEATHERSTRIP	SERVICEABLE	85.10	-
1	LH REAR DOOR INNER LOCK	TO REPAIR SEE LABOUR	191.50	-
1	LH REAR DOOR GLASS REGULATOR	SERVICEABLE	223.40	-
1	LH REAR DOOR GLASS REGULATOR MOTOR	SERVICEABLE	160.50	-
1	LH REAR DOOR TRIM BOARD	SERVICEABLE	597.00	-
1	LH REAR DOOR LOWER STICKER	NECESSARY	30.00	30.00
1	LH ROCKER PANEL STICKER	NECESSARY	30.00	30.00
1	LH REAR FENDER	BENT	1,892.00	1,768.30
1	LH REAR SPORTS RIM	DENTED	671.30	671.30
	LESS 20% DISCOUNT		-1,157.82	-860.92
			4,631.28	3,443.68
<b><u>LABOUR</u></b>				
	TO REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	120.00
	TO CONDUCT WATER TEST TO CHECK FOR LEAKAGE.		50.00	20.00
	TO REMOVE/REFIX TRIMS,SPEAKERBOARD,SEATS,ETC TO FACILITATE REPAIRS.		280.00	120.00
	TO REMOVE/REFIX FUEL TANK TO ASSIST REPAIR.		180.00	60.00
	TO CONDUCT WHEEL ALIGNMENT (COMPUTERISE).		120.00	60.00
	TO TRANSFER NEW RIM TO TYRE AND BALANCING.		50.00	20.00
	TO RUSTPROOF ACCIDENT DAMAGE AREA.		200.00	60.00
	TO STRAIGHTEN LH FRONT DOOR,LH REAR FENDER,LH ROCKER PANEL INNER PANEL.CUT OUT/RE-WELD LH REAR FENDER INCLUDING REPLACEMENT OF PARTS.INCLUSIVE OF THE REPAIR OF LH REAR DOOR INNER LOCK.		1,500.00	800.00
	TO SPRAY PAINT ON LH REAR FENDER,OUTER/INNER LH ROCKER PANEL,LH REAR DOOR,LH FRONT DOOR.		1,300.00	800.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER LH REAR DOOR MECHANISM.		100.00	60.00
			3,900.00	2,120.00
GRAND TOTAL			8,531.28	5,563.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,450.00

Report Ref No. CS/AGI21010629/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.