

TRANS EUROKARS PTE LTD 27A TANJONG PENJURU, SINGAPORE 609042 ESTIMATE COST OF REPAIRS

(1) EUROKARS SERVICES

		The second secon	The American Street Conference on the	Name and Additional Property of	and the second s	NO DESCRIPTION OF THE PERSON O	The second secon	WIP:	42677	
INDIA	INTERNATION	NAME:					EXCESS:			
64 CECIL STREET			ADDRESS:					DATE:	12-Oct-21	
	0 & #05-00 IOB BI	UILDING								
	PORE 049711									
ATTN		MOTOR CLAIMS	TEL:							
FAX:				-	-	CONTACT PERSON:	JESS			
VEH		SMC2692U	DATE IN:		-		TYPE OF CLAIM:	THIRD PARTY	CLAIM	
CHASSIS NO: JM6BN24A8J0220485		MILEAGE:				POLICY NO.:				
MODE	l:	MAZDA 3	DATE REG.:	TURE (8-Jun-	STATE OF TAXABLE PARTY.	POLICI NO.	•		
				Parts De						
					1st	Supp	PARTS NO	REVISED	PRICES	
NO	DESCRIPTION			QTY	ist		MB63B-50-221ABB		\$ 996.70	
	REAR BUMPER / [[]		.4.	1	1		MDFR5-50-251		\$ 5.40	
				1	V		MB45C-50-260		\$ 564.20	
3				1			MBHN1-50-0Z1A		\$ 10.80	
4				4	1		MBHN9-50-369		\$ 58.80	
5	BRACKER CENTER LOWER REAR BUMPER			1	. /		MEA01-50-037		\$ 16.00	
-				2	V		MB63B-50-EK1 BB		\$ 15.80	
7	7 COVER TOWING HOOK RH ?			1	/		MBBM4-50-355		\$ 45.00	
8	RIVET / NIC			10	V	-	MB45A-56-146A		\$ 6.00	
9	FASTENER	- nec		2	V		MB43A 30 140A			
						_	TOTAL PARTS		\$ 1,718.70	
							TOTAL PARTS			
							TOTAL PARTS COST		\$ 1,718.70	
	-						TOTALTAKTS GOOT			
			CII	PPLE	AENT	ADV				
			50				PARTS NO	REVISED	PRICES	
NO	DESCRIPTION			QTY	1st	Supp	PARTS NO			
1										
2										
3										
							Tarana Barra		\$ -	
							TOTAL PARTS		1	
							7200 STRIP COST		\$ -	
							TOTAL PARTS COST		1	
Labour Description								DEMICED	PRICES	
								REVISED	PRICES	
. 1	TO REPLACE REAR BUMPER. TO REPAIR REAR END PANEL.						661	\$ 1,980.00		

ESTIMATE Page 1 of 2

2		639	\$ 2,5	20.00			
3	MZ-BR-REVSEN	330	\$ 6	60.00			
4	MZ-BR-ELECTF	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	erfolge bei troppig follow die fer in vier en spelant and was to be followed tropping and an executive and and	200	\$ 2	50.00	
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	(COLOR VIII - NECESSARIANI DA TAMA ANTARA ARRAGA DE PROPERTO ARRAGA POR ARRAGA POR ARRAGA ARR	250	\$ 3	00.00	
6	MZ-BR-SUNDR	MZ-BR-SUNDRI SUNDRIES.					
1	AND SHOULD THE PROCESS BEFORE THE F NOTE THAT SI THE REPAIRS,	AN ESTIMATE FROM VISUAL INSPECTION THERE BE MORE DAMAGES FOUND DURING OF REPAIRING, YOU WILL BE INFORMED REPAIRS ARE BEING CARRIED OUT. TAKE HOULD YOU DECIDE NOT TO PROCEED WITH A QUOTATION FEE OF \$400 WILL BE DRDINGLY FOR MAN-HOURS INVOLVED IN R PARTS PRICE AS WELL AS LABOUR SUPPLEMENTARY LABOUR DESCRIPT #N/A	TOTAL LABOUR TOTAL PARTS TOTAL LESS EXCESS TOTAL AFTER EXCESS GST 7% GRAND TOTAL	\$ - \$ - \$ - \$ - \$ - \$ - REVISED	\$ 1,7 \$ 7,4 \$ 5 7,4 \$ 5 8,0	60.00 718.70 178.70 478.70 523.51 002.21	
2		#N/A					
	REMARKS:		TOTAL LABOUR	\$ -	\$	-	
	THIS IS ONLY	AN ESTIMATE FROM VISUAL INSPECTION	TOTAL PARTS	\$ -	\$	•	
	AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED TOTAL			\$ -	\$	•	
	BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE PERAIRS A QUIOTATION FEE OF \$400 WILL BE TOTAL AFTER EXCESS				\$	-	
	NOTE THAT SE	A OLIOTATION FEE OF \$400 WILL BE					
	THE REPAIRS,	A QUOTATION FEE OF \$400 WILL BE ORDINGLY FOR MAN'HOURS INVOLVED IN R PARTS PRICE AS WELL AS LABOUR	GST 7%	\$ -	\$	-	

Steve (LKK) 19/10/21, 10.30 83928813

TRANS EUROKARS PTE LTD

me pe 3 dys

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudic+" basis
- No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to anal approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

ESTIMATE Page 2 of 2