

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CS/CTI21010636/UTY3Q2

Date:

05/11/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMCVSNW00103362001

Claimant Vehicle No : FBL5782G**Insured Vehicle No :** YP2581X

Date of Loss: 16/09/2021

Nature of Claim: TP

Claim No: SNM21D205276/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBL5782G**

Make & Model: YAMAHA YZF-R155, 155cc

Engine No: 2PB2002787

Reg. Date: 23/12/2016 (Man. Year: 2016)

Chassis No: ME1KG0694H2002006

Colour: Blue

Odometer: 0 km

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	90/80-17	Rear Tyre Size:	140/70-17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,567.50	1,431.00	136.50	8.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	310.00	300.00	10.00	3.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,877.50	1,731.00	146.50	7.80
Approved Total (Overridden) (S\$)		1,300.00		

Nett Amount (S\$)**1,877.50****1,300.00****577.50****30.76**INSPECTION

Date of Assignment: 15/10/2021

Date Inspected: 15/10/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Teo Spray Painting (HQ)
BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558
Singapore 539187**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Nov 2021)	
Parts:	N/A	YAMAHA YZF-R155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL5782G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EXHAUST PROTECTOR	Torn	65.00 FL	*65.00 FL
2	1		*EXHAUST COVER	Cut	55.00 FL	*55.00 FL
3	1		*BRAKE PANEL	Bent	45.00 FL	*45.00 FL
4	1		*FRONT SIGNAL RH	Broken	45.00 FL	*45.00 FL
5	1		*REFLECTOR	Broken	18.00 FL	*18.00 FL
6	1		*SIDE MIRROR RH	Grazed	58.00 FL	*58.00 FL
7	1		*BRAKE LEVER	Scratched	25.00 FL	*25.00 FL
8	1		*REAR FENDER BRACKET	Bent	75.00 FL	*75.00 FL
9	1		*TAIL LIGHT	Broken	180.00 FL	*180.00 FL
10	1		*LOWER FENDER	Cracked	35.00 FL	*35.00 FL
11	1		*REAR MUDGUARD	Distorted	45.00 FL	*45.00 FL
12	1		*REAR LOWER FENDER	Distorted	65.00 FL	*65.00 FL
13	1		*LICENCE PLATE LIGHT	Cracked	48.00 FL	*48.00 FL
14	1		*REAR SIGNAL LH	Twisted	45.00 FL	*45.00 FL
15	1		*REAR SIGNAL RH	Twisted	45.00 FL	*45.00 FL
16	1		*PILLION SEAT	Warped	85.00 FL	*85.00 FL
17	1		*TAIL COVER LH	Cracked	85.00 FL	*85.00 FL
18	1		*TAIL COVER RH	Cracked	85.00 FL	*85.00 FL
19	1		*TAIL COVER CENTER	Cracked	38.00 FL	*38.00 FL
20	1		*SEAT LOCK COVER	Damaged	48.00 FL	*48.00 FL
21	1		*REAR LICENCE PLATE	Bent	18.00 FS	*12.00 FS
22	1		*CLUTCH LEVER (SCRATCHED)	Not Consistent With The Impact	25.00 FL	*- FL
23	1		*SIDE FAIRING RH	Cut	120.00 FL	*120.00 FL
24	1		*SIDE FAIRING LH	Not Necessary	120.00 FL	*- FL
25	1		*REAR BOX	Cut	120.00 FS	*120.00 FS
26	1		*REAR BOX RACK	Twisted	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Sub Total (S\$)						1,713.00
- List Item Discount on L Items 10.00/10.00% (S\$)						145.50
Total Parts (S\$)						1,567.50

1,562.00

131.00

1,431.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	60.00	60.00
2	LABOUR CHARGES	New	250.00	240.00
Gross Labour Cost (S\$)			310.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >