




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



Reference No.: 141021

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 14.10.2021

Lee Eng Yeow (Li Rongyao)
27 Hazel Park Terrace #14-03
Singapore 678949.

Volvo XC60 TS

Estimate Repair Cost for Vehicle Reg. No: SKT6966M


- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 Pc. Front Bonnet <i>key</i>		2,980.00	X
1Pc. Front Grille <i>cut / scratch</i>		1,260.00	✓ 1150.00
1 Pc. Front Grille Logo <i>h/c</i>		148.00	✓
6 Pcs. Front Grille Clips <i>h/c</i>	@ 6.00	36.00	✓ 15/- SN
1 Pc. Front Head Lamp Assy. <i>h/s mounty crack</i>		4,500.00	✓ 2465.32
1 Pc. Front Bumper <i>disturb</i>		2,845.00	✓ 1645.32
1 Pc. Front Bumper <i>Sponge lower Centre Cover crack</i>		483.00	✓ 483.00
1 Pc. Front Bumper Beam <i>h/c</i>		351.00	X
1 Pc. Front Bumper Reinforcement <i>h/c</i>		1,620.00	X
1 Pc. Front Bumper Lower Grille <i>h/c</i>		265.00	X
2 Pcs. Front Bumper Side Retainer <i>SVZ</i>	@ 145.00	290.00	X
10 Pcs. Front Bumper Clips <i>h/c</i>	@ 8.00	80.00	✓ 30/- SN
2 Pcs. Front Bumper Lower Corner Cover <i>h/c</i>	@ 190.00	380.00	X
2 Pcs. Front Head Lamp Holder <i>crack h/s o/s h/c</i>	@ 143.00	286.00	✓ 75.00
1 Pc. Front Bonnet Lock <i>h/c</i>		268.00	X
1 Pc. Front No. Plate <i>& BOX 1st</i>		60.00	✓ 45/- SN 20/-
1 Pc. Rear Boot Tail Gate Handle <i>h/c</i>		398.80	X
1 Pc. Rear Boot Inner Garnish <i>h/c</i>		798.00	X
1 Pc. Rear Boot XC60 Emblem <i>h/c</i>		166.00	✓ 148.70
1 Pc. Rear Boot Volvo Emblem <i>h/c</i>		147.00	✓ 131.50
1 Pc. Rear Boot Volvo TS Emblem <i>h/c</i>		145.00	✓ 127.80
1 Pc. Rear Boot Lock <i>h/c</i>		599.00	X
1 Pc. Rear Bumper <i>tom</i>		2,428.00	✓ 1897.00
2 Pcs. Rear Bumper Bracket <i>o/s h/c h/s broken</i>	@ 155.00	330.00	✓ 96.70
1 Pc. Rear Bumper Reinforcement <i>SVZ</i>		970.00	X
1 Pc. Rear Bumper Lower Pad Spoiler <i>disturb</i>		782.00	✓ 486.00
2 Pcs. Rear Bumper Side Retainer <i>o/s h/c h/s crack</i>	@ 145.00	290.00	✓
1 Pc. Rear Bumper Dust Garnish <i>tom</i>		310.00	✓ 202.00
10 Pcs. Rear Bumper Dust Garnish Clips <i>h/c</i>	@ 6.00	60.00	✓ 15/- SN
10 Pcs. Rear Bumper Clips <i>h/c</i>	@ 6.00	60.00	✓ 30/- SN
1 Pc. Rear Air Duct <i>deformed</i>		199.00	✓ 79.20
1 Pc. Rear Bumper top Garnish <i>cut</i>		410.00	✓ 345.00



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



2 Pcs. Rear Bumper Parking Sensor 1pc Dem @ 381.00	762.00	✓	210.00
1 Pc. Rear Exhaust Chrome chrome rep	480.00	✓	363.80 X
1 Pc. Rear Exhaust Bracket HW	59.00	X	
2 Pcs. Rear Exhaust Mounting HW @ 50.00	100.00	X	
1 Pc. Rear Exhaust broken	1,690.00	✓	924.00
1 Pc. Rear Exhaust Hard Cover torn	709.00	✓	315.00
1 Pc. Rear Reflector broken	188.00	✓	
1 Pc. Rear End Panel rep	3,636.00	X	
1 Pc. Rear End Panel Garnish HW	781.00	X	
1 Pc. Rear Centre Protect Plate HW	780.00	X	
1 Pc. Rear Parking Wire svz	599.00	X	
1 Pc. Rear Exhaust Gasket H/c	59.50	✓	
1 Pc. Rear Windscreen Moulding HW HW	299.00	X	
1 Set. Rear Windscreen Sealant with Repair Kit HW	220.00	X	
1 Pc. Rear Bumper Lower Centre Pad cut / torn	699.00	✓	641.70

Total (Panels / Parts): 34,097.30 (SGD)

LABOR CHARGES

To check wiring, remove & refit wire on all accident Affected area.	180.00	30/-
To knocking, straightening, repair & renew on all Accident damage affected area.	1,200.00	1000/-
To respray painting on all accident affected area.	1,300.00	1000/-
To remove & refit interior garnish sideboard & All affected area.	280.00	80/-
To remove & refit rear windscreen.	200.00	HW
To diagnostic check on control unit, reset memory To identification standard & reset head lamp unit.	300.00	150/-
To rust proof all accident affected area.	120.00	40/-

15/10/2021 @ 18:00


Total (Labor Charges): 3,580.00 (SGD)

HA Arthur to dyc.

L/Sun

Ryan

2kk And




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



TOTAL COST SUMMARY

PANELS / PARTS	34,097.30
LABOR CHARGES	3,580.00

Grand Total: 37,677.30 (SGD)

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

PARTS
11963.74 *SH 110.00* *Labor 2300.00*
5% 11,365.55

13,775.55
4/5 11,000/-