



KT GARAGE PTE LTD UEN: 201906115R
Auto Bay@ Kaki Bukit Entrance A
BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

GARAGE

Date : 15/10/2021

Total Pages : 1

TO: **India International Insurance Pte Ltd**
64 Cecil Street #04-02 IOB Building
Singapore 049711

Our Customer : KT Leasing Pte Ltd
Vehicle No : **PC9145B**
Model : Toyota hiace

Manufacture Year : 2019

Date of Accident : 28/09/2021

Total Estimate Repair Days : 3

Attn : Motor Claim Department
Email : claimsdept@sg.cntaiping.com

Re: Repair Estimate For Third Party Claims against SNB9046H

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Frt bumper	1	\$387.40	\$387.40	grossed ✓
2	Frt bumper clip	8	\$5.50	\$44.00	new ✓
3	Side retainer LH	1	\$128.70	\$128.70	new X
4	Frt fog lamp LH	1	\$269.50	\$269.50	new X
	Sub Total			\$829.60	
	Less 25%			\$207.40	
	Sub Total 1			\$622.20	
	Total Spare Parts			\$622.20	
B.	Labour				
1	To knock and straighten damage panel, cut & weld necessary portion and realign the same.			\$300.00	180
2	To check all lighting and wiring			\$80.00	20
	Total Labour			\$380.00	
	Total Repair Cost			\$1,002.20	
* The above quoted are exclusive of GST.					

Yours faithfully,

Darla
f KT Garage Pte Ltd



not Affirmed
Liu
the pte Affirming
including parts

1 day
p/p
18/10/21

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	
The Repairer of the following: Resurvey, replacement parts, painting	
• No delay in commencing work during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Acknowledged by Repairer	
Signature:	
Date:	