

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No: SJU7741U
Make and model: Toyota Altis
Chassis: MR053ZEE106162788

Qty	Spare parts		2009 List price	
1	Bootlid	\$	745.70	909.70 BTV
1	Bootlid "1.6" emblem	\$		✓ 28.10
1	Bootlid centre emblem	\$		✓ 45.67
1	Bootlid "Corolla" emblem	\$	46.60	61.60 } NEC
1	Bootlid "Altis" emblem	\$		✓ 49.85
1	Bootlid "LX" emblem	\$		✓ 36.50
1	Bootlid chrome moulding	\$		234.60 NDX
1	Bootlid RH lamp	\$	228.20	✓ 228.90 BRV
1	Bootlid RH lamp sponge gasket	\$		✓ 21.30 NECV
1	Bootlid LH lamp	\$		✓ 228.90 BRV
1	Bootlid LH lamp sponge gasket	\$		✓ 21.30 NECV
1	Bootlid lock	\$		✓ 126.80 JMW
1	Bootlid lock catch	\$		45.70 NDX
1	Bootlid RH hinge	\$		148.50 } NDX
1	Bootlid LH hinge	\$		148.50
1	Bootlid weatherstrip	\$		✓ 194.70 DISV
1	Bootlid inner trim	\$	174.10	251.60 TNV
1	Rear bumper	\$	482.30	523.90 BRV
1	Rear bumper RH reflector	\$		55.70 } NDX
1	Rear bumper LH reflector	\$		55.70
1	Rear bumper RH side retainer	\$	35.00	57.80 } NECV
1	Rear bumper LH side retainer	\$	35.00	57.80
1	Rear bumper RH side holder bracket	\$		✓ 46.95 } DDV
1	Rear bumper LH side holder bracket	\$		✓ 46.95
1	Rear bumper sponge with reinforcement	\$		✓ 175.90 BRV
1	Rear bumper RH impact bracket	\$	85.60	97.90 DDV
1	Rear bumper LH impact bracket	\$	85.60	97.90 DDV
1	RH taillamp	\$	362.00	438.00 BRV
1	RH taillamp sponge gasket	\$		✓ 22.50 NECV
1set	RH taillamp lock clips	\$		✓ 12.00 NECV
1	RH taillamp lower bracket	\$		✓ 45.70 BRV
1	LH taillamp	\$	362.00	438.00 BRV
1	LH taillamp sponge gasket	\$		✓ 22.50 NECV
1set	LH taillamp lock clips	\$		✓ 12.00 NECV
1	LH taillamp lower bracket	\$		✓ 45.70 BRV
1	End panel	\$		✓ 590.60 DDV

1	End panel inner garnish	\$	✓ 202.70	BRV
1	Rear windscreen glass rubber moulding	\$	138.60	NNX
1	Rear RH fender	\$	945.00	NNX
1	Rear RH fender inner trim	\$	381.80	NNX
1	Rear LH fender	\$	945.00	NNX
1	Rear LH fender inner trim	\$	381.80	NNX
1	Spare tyre panel	\$	R 817.10	DDX
1	Spare tyre panel cover board	\$	276.60	BRV
1	Exhaust silencer	\$	718.90	NNX
1	Exhaust silencer gasket	\$	38.20	NNX

\$ 4,896.02 10,584.22
 -25% \$ 1,224.01 2,646.06
 \$ 3,672.02 7,938.17

Qty Spare parts

		Special Nett price	
1set	Rear bumper clips	\$ 30.00	70.00 TRCV
1set	Rear bumper reverse sensor	\$ 200.00	280.00 SCV
1	Rear windscreen glass sealant	\$	70.00
1	Rear windscreen glass inner seal	\$	50.00
1	Rear RH fender joint sealant	\$	70.00
1set	Rear RH fender inner trim clips	\$	70.00
1	Rear LH fender joint sealant	\$	70.00
1set	Rear LH fender inner trim clips	\$	70.00
1	End panel joint sealant	\$ 30.00	60.00 NECV
1set	End panel inner garnish clips	\$ 30.00	50.00 NECV
1	Bootlid reverse camera	\$	550.00 NNX
1set	Roof lining clips	\$	90.00
1	Spare tyre panel joint sealant	\$	70.00
		<u>290.00</u>	NNX

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels	\$ 800.00	1,800.00 ✓
Spray painting on affected panels	\$ 800.00	1,400.00 ✓
Check wiring and lighting system	\$	80.00 NNX
Apply rust coating chemical on affected panels	\$	100.00 NNX
Remove and replace bootlid reverse camera to assist repair	\$	100.00 NNX
Remove and replace bootlid inner components to new bootlid	\$ 80.00	100.00 ✓
Remove and replace rear inner trims, garnish, roof lining, seats and boards to	\$	280.00 NNX

assist repair

Remove and replace rear bumper reverse sensors to assist repair

\$ 60.00 -100.00 ✓

Remove and replace exhaust silencer and rubber mouldings to assist repair

\$ 120.00 NNA

1,740.00

Total: \$ 13,588.17

Survey and resurvey

18/10/2021

16 IS L3

TGU in line

Lamp sum repair

Repair days 7

Parts	3,672.02
SN	290.00
Labour	1,740.00
	5,702.02
	1,140.40
	4,561.61

LS 4550/2

TGU in line
25/10/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: