

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%20	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: AIG

Vehicle No : PC 8877 D

Make & Model : TOYOTA HIACE

DATE: 13/10/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAILGATE 1925	1	\$ 2,243.00	\$ 2,243.00
2	TAILGATE WINDSCREEN MOULDING	1	\$ 185.00	\$ 185.00
3	TAILGATE LOGO	1	\$ 92.30	\$ 92.30
4	TAILGATE EMBLEM(HIACE)	1	\$ 94.80	\$ 94.80
5	TAILGATE CHROME MOULDING 180	1	\$ 254.00	\$ 254.00
6	TAILGATE CAR PLATE LAMP	2	\$ 89.00	\$ 178.00
7	TAILGATE OPENNER HANDLE	1	\$ 178.90	\$ 178.90
8	TAILGATE KEY LOCK photo 156	1	\$ 256.90	\$ 256.90
9	TAILGATE INNER LOCK 270	1	\$ 340.00	\$ 340.00
10	TAILGATE INNER LOCK COVER 98-96	1	\$ 124.00	\$ 124.00
11	TAILGATE INNER LOCK MECHANISM photo 251	1	\$ 312.00	\$ 312.00
13	TAILGATE AUTO LOCK ACTUATOR photo 189	1	\$ 289.00	\$ 289.00
14	TAILGATE LOCK CATCH	1	\$ 58.00	\$ 58.00
15	TAILGATE WEATHERSTRIP 329	1	\$ 395.00	\$ 395.00
16	TAILGATE SIDE RUBBER 25 50	2	\$ 30.00	\$ 60.00
17	TAILGATE SIDE STOPPER(MALE) 230 60	2	\$ 45.00	\$ 90.00
18	TAILGATE SIDE STOPPER(FEMALE) 230 60	2	\$ 45.00	\$ 90.00
19	TAILGATE INNER BOARD 165	1	\$ 579.80	\$ 579.80
20	TAILGATE INNER BOARD HANDLE	1	\$ 197.00	\$ 197.00
22	TAILGATE HINGE	2	\$ 123.00	\$ 246.00
23	TAILGATE ABSORBER DAMPER	2	\$ 298.70	\$ 597.40
24	TAILLAMP 366 732	2	\$ 498.00	\$ 996.00
25	TAILLAMP LOWER GARNISH 101	2	\$ 167.00	\$ 334.00
26	TAILLAMP LOWER GARNISH RETAINER	2	\$ 65.00	\$ 130.00
28	REAR BUMPER 479	1	\$ 568.00	\$ 568.00
29	REAR BUMPER SIDE RETAINER	2	\$ 55.00	\$ 110.00

30	REAR BUMPER INNER STEP PANEL	282	1	\$	347.20	\$	347.20	11
31	REAR BUMPER LOWER BRACKET	120 2	4	\$	60.00	\$	240.00	11
32	REAR END PANEL (EXTEND)	14x RH 17x R2	2	\$	295.00	\$	590.00	11
33	REAR END PANEL (INNER)	RX 625	1	\$	871.00	\$	871.00	11
34	REAR END PANEL (OUTER)	475	1	\$	597.00	\$	597.00	11
35	REAR END PANEL TOP GARNISH	209	1	\$	385.00	\$	385.00	11
36	REAR FLOOR PANEL		1	\$	2,690.00	\$	2,690.00	11
37	REAR FLOOR MAT	84x20	1	\$	1,262.40	\$	1,262.40	11
38	REAR FENDER INNER TRIM		2	\$	1,045.00	\$	2,090.00	11
39	REAR FENDER AIR VENT		2	\$	65.00	\$	130.00	11
40	SPARE TYRE BRACKET	nn x 298	1	\$	598.00	\$	598.00	11
41	SPARE TYRE BRACKET BOLT	nn x 100	1	\$	167.00	\$	167.00	11
42	SPARE TYRE BRACKET NUT	nn x 45	1	\$	120.00	\$	120.00	11
43	EXHAUST SILENCER		1	\$	759.00	\$	759.00	11
44	EXHAUST MOUNTING		2	\$	45.00	\$	90.00	11
45	EXHAUST GASKET		1	\$	50.00	\$	50.00	11

7764.10 8882200 Subtotal : \$ 19,985.70

5823.07 6684207 Less 25% \$ 4,996.43

Parts Total : \$ 14,989.28

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00	11
2	REAR BUMPER CLIP SET	1	\$ 65.00	\$ 65.00	11
3	TAILGATE SEALANT	1	\$ 80.00	\$ 80.00	11
4	TAILGATE CENTER MOULDING CLIP SET	1	\$ 38.00	\$ 38.00	11
5	TAILGATE INNER BOARD CLIP SET	1	\$ 75.00	\$ 75.00	11
6	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	11
7	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	11
8	TAILGATE STICKER (70KM/H)	1	\$ 40.00	\$ 40.00	11
9	TAILGATE STICKER (EMERGENCY DOOR)	1	\$ 20.00	\$ 20.00	11
10	TAILLAMP CLIP SET	1	\$ 32.00	\$ 32.00	11
11	REVERSE CAMERA	1	\$ 800.00	\$ 800.00	11
12	REAR END PANEL (EXTEND) SEALANT	1	\$ 120.00	\$ 120.00	11
13	REAR END PANEL (INNER) SEALANT	1	\$ 150.00	\$ 150.00	11
14	REAR END PANEL (OUTER) SEALANT	1	\$ 150.00	\$ 150.00	11
15	REAR FLOOR PANEL INSULATION SEAL	1	\$ 350.00	\$ 350.00	11
16	REAR FLOOR PANEL TOP BOARD	1	\$ 1,600.00	\$ 1,600.00	11
17	REAR FENDER INNER TRIM CLIPS	1	\$ 60.00	\$ 60.00	11
18	LAST ROW PASSEGER SEAT SET	1	\$ 1,800.00	\$ 1,800.00	11
19	LAST ROW PASSEGER SEAT BRACKET SET	1	\$ 800.00	\$ 800.00	11

				200mm ✓
20	REVERSE SENSOR	1	\$ 300.00	\$ 300.00
				1092.
			SPECIAL NETT	\$ 6,670.00
LABOUR (REAR)				PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	1000		\$	1,800.00
TO SPRAY PAINT AFFECTED AREA	1000		\$	1,800.00
REAR LIGHTING WIRING AND BULB CHECKING.	30		\$	100.00
TRANSFER TAILGATE MECHANISM.	60		\$	150.00
REMOVE AND REFIX TAILGATE WINDSCREEN	120		\$	200.00
REMOVE AND INSTALL REAR-VIEW CAMERA. ADJUST CAMERA ANGLE.	30		\$	150.00
REMOVE AND REPLACE REVERSE SENSOR.	30		\$	150.00
CONDUCT WATER LEAKAGE TEST.	20		\$	100.00
REMOVE AND REFIX REAR SEAT AND COMPARTMENT LINING TO FACILITATE REPAIR.	200		\$	1,000.00
REMOVE AND REFIX REAR EXHAUST	60		\$	250.00
				2550.
			LABOUR TOTAL	\$ 5,700.00

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Acknowledged by Repairer
Signature: _____
Date: _____

San Francisco
7 days.

$$\begin{array}{r} 5823.07 \\ 1092 \\ 2550 \end{array}$$

9465.07

2/3 7500
28 days