



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2107571

INV Date 03/11/2021

Reference CC4/FCI21010649/Gpa3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBC 8290L

Insured Veh. FBG 9775C

Claim No. D21002213MFCE

Policy No.

Accident Date 21/07/2021

Inspection Date 18/10/2021

Description	Total
Survey Inspection	226.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	226.00
GST (7%)	15.82
Grand Total	241.82

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CC4/FCI21010649/Gpa3q2 Date: 03/11/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBG 9775C	Veh. Inspected	GBC 8290L
Policy No.		Coverage (\$)	0.00
Claim No.	D21002213MFCE	Excess (\$)	0.00
Assign From	VIC	Assign Date	15/10/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200 1.5L	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VSKYBAM20U0059974	Colour	WHITE
Odometer	187042 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	ARIVO	6 mm
L/H Front Tyre	175/70 R14	ARIVO	6 mm
R/H Rear Tyre	175/70 R14	ARIVO	6 mm
L/H Rear Tyre	175/70 R14	ARIVO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/07/2021	Inspection Date	18/10/2021
Survey held at	ETHOZ PROTECT PTE LTD 22 TAMPINES STREET 92 SINGAPORE 528876		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 8290L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL LAMP LH	SCRATCHED	277.20	277.20
1	LH SIDE SKIRT	CRACKED	225.00	225.00
1	LH SIDE MIRROR (ROUND MIRROR SMALL)	MISSING	35.00	35.00
	LESS 30% DISCOUNT		-161.16	-161.16
			376.04	376.04
SPECIAL NETT ITEMS				
1	COMPANY LETTERING (SN)	NOT NECESSARY	80.00	-
			80.00	-
LABOUR				
	PANEL BEATING FOR QUARTER PANEL LHS .		400.00	200.00
	SPRAY PAINTING FOR QUARTER PANEL LH ,SILDING DOOR LH ,FRONT DOOR AND SURFACE FRONT LH FENDER.		1,000.00	800.00
			1,400.00	1,000.00
GRAND TOTAL			1,856.04	1,376.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CC4/FCI21010649/Gpa3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 8290L

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 8290L

RE-INSPECTION

