

SM 62533A.

Honda Civic

MRHFC5650JT002054

TPAIG.

Xiao Tong.

Rear Bumper	Distorted	617.70	✓
Rear Bumper Clips.	New	80(SN)	✓
Rear Bumper Side Holder LH.	Damaged	24.50.	✓
Rear Bumper Reflector LH.	Not new	30.40.	X.
Rear Bumper Side Grille LH.	Not	171.60.	✓
Rear Bumper Reinforcement.	Not	260.40	X.
Rear Bumper Lower Garnish.	Distorted	166.90.	✓
Reverse Sensor.	Not	280(SN) 200(SN)	X
Rear End Panel	Repaired	348.20.	X
Rear End Panel Top Garnish.	Not new	91.70	X
Rear End Panel Top Garnish Clips		20(SN)	X
Rear End Panel Sealant.	Not	60(SN)	✓
Tailgate LH	Crushed	330.50	✓
Tailgate Panel LH.	Dented	158.60.	✓

SMG2533A.

Bootlid	Buckled		554.90. ✓
Bootlid Lock	{	NH	185.40 X
Bootlid Weatherstripe.		ner	159.20. X.
Bootlid Reflector LH.		crushed	279.20. ✓
Honda Logo	{	NH	35.60 ✓
i-Vtec Emblem.		ner	40.80 ✓
Rear LH Fender		Distorted	920.80. ✓
Rear LH Fender Air Vent.		Distorted	55.90 ✓
Rear LH Fender Inner Shield		horn	145.90 ✓
Rear LH Fender Inner Shield clips.		ner	30(SN) ✓
Rear LH Fender Inner Trim		ner ner	258.20 X
Rear LH Fender Inner Trim clips.		NH	30(SN) X
Rear LH Fender Inner Trim clips.		ner	30(SN) X
Rear LH Fender Quarter Glass Molding.			65.60 ✓
Rear LH Fender Quarter Glass Sealant		ner	40(SN). ✓
Fuel Tank Cover. Lid.		Deformed	185.20 ✓
Fuel Tank Inner Cover.		Deformed	85.10. ✓

SMG2533A.

Rees Windscreen Moulding.	} New	156.70.	✓
Rees Windscreen Sealant.		60(SN).	✓
Rees LH Wheel Rim.	cut	800(SN) 500(SN)	
Rees LH Tyre.	Punctured	300(SN) 200(SN)	
Rees LH Lower Arm.	Bent	384.40	✓
Rees LH Shock Absorber	Bent	324.10	✓
Rees LH Knuckle Arm.	Pang d	358.50	✓
Rees LH Wheel Hub c/w Bearing.	Pang d	290.40.	✓
Rees LH Control Arm.	} Bent	214.70.	✓
Rees LH Stay Arm.		220.40.	✓
Rees LH Trailing Arm.		349.40	✓
Rees Cross Member	Bent	949.20	✓
Rees LH Door	Distorted	878.20.	✓
Rees LH Door Lock	Damaged	272.80.	✓
Rees LH Door Weatherstripe.	cut	198.50	✓
Rees LH Door Outer Handle.	MP MR	300(SN).	+

SMG2533A.

Rees LIT Door Inner Trim Board ~~needed~~ 469.80 ✓

Rees LIT Door Inner Trim Board clips. ~~m~~ 30(SN). ✓

Rocker Panel Outer Skirting LH. ~~del~~ 620.80. ✓

Rocker Panel Outer Skirting clips. ~~m~~ 30(SN) ✓

SMG2533A.

Front Number Plate	} new new	30(SN)	X
Front Number Plate Holder		30(SN)	X.
Front Bumper Distorted		579.90	✓
Front Bumper Lips. new		30(SN)	✓
Front Bumper Side Holder LH. Bumped		26.90.	✓
Front Bumper Reinforcement. Dented		376.90	✓
Front Bumper Side Grille LH. Dented		98.20	✓
Front Bumper Lower Garnish. Centre. new		400(SN)	X
Front Bumper Lower Garnish LH. Distorted		300(SN)	200(SN)
Front Grille	crushed	285.50.	✓
Front Grille Logo	} new	38.40	✓
Front Grille clips.		20(SN)	✓
Handcup LH	crushed	1120.60	✓
Handcup Lower Bracket LH.	crushed	65.90	✓
Handcup Top Garnish LH. Int		108.20.	✓

SMG2533A.

Bonnet	Repis	683.50	X
Front LH Fender	Distorted	520.70	✓
Front LH Fender Inner Shield	Defunct	429.40	✓
Front LH Fender Inner Shield Clips.	new	30(SN)	✓
Front LH Fender Extension Panel.	Repis	394.20	X
Front LH Wing Mirror.	Defunct	640.50	✓
Front Support Panel Assy.	Cracked	665.20	✓
Air Con Condenser	new	788.80	X
Air Con Condenser Side Guide	Defunct	45.90	✓
Air Con Condenser Side Guide Clips.	new	20(SN)	✓
Air Resonator Tank	Cracked	197.10	✓
Front Support Panel Top Garnish.	Defunct	142.30	✓
Front Support Panel Top Garnish Clips.	new	20(SN)	✓
Coolant.	new	50(SN)	✓
Engine Mounting	x 2	285.3 x 2 = 570.60	✓
Gearbox Mounting	Defunct	278.40	✓

SMG2533A.

Front LH Lower Arm.	Best	291.40. ✓
Front LH Shock Absorber	new	328.80 +
Front LH Knuckle Arm.	And.	342.10 ✓
Front LH Wheel Hub c/w Bearing.	And	310.40. ✓
Front LH Anti Roll Linkage	} XHP new	94.10. +
Steering Rack and Pinion.		1976.10. +
Steering Crossmember.		1455.30 +
Front LH Wheel Rim.	lit	8w(sw) 5w(sw)
Front LH Tyre.	XHP new	300(sw) +
Front LH Door	Revis	895.40. +
Front LH Door Lock	} XHP new	269.90. +
Front LH Door Weatherstripe		190.40. +

SMG 2533A.

Panel Beating	3400 2100
Spray Painting	2800 1900
Wiring.	100 60
To remove reverse sensor	100 50
To spray tuff coat	250 120
To remove upholstery.	150 60
To transfer bootlid fittings.	150 60
To remove rear windscreen.	180 120
To remove fuel tank.	150 60
To remove rear undercarriage.	300 220
To perform wheel alignment.	150 80
To transfer front and rear door fittings.	300 80
To remove condenser and to top up air con gas }	120 60

SMG2533A.

To remove radiator and to
top up coolant.

~~120.60~~

To replace engine and gearbox mountings.

~~380.250~~

~~340.220~~

To remove front undercarriage.

To remove Steering rack and pinion }
and steering crossmember }

~~220.120.~~

To clean up interior upholstery.

~~500.300~~

Towing Fees.

60. ✓

List: 16261.20

Gen 20%: 13008.96

2050

S.N: ~~2020~~

Labour: 5980

21038.96

Total: ~~21038.96~~

L/S: 16.8K

19 Days

16.8K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: