



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. BICYCLE

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REPLACEMENT OF GARMIN FENIX 6 SAPPHIRE SMARTWATCH	DAMAGED	999.00	999.00
1	REPAIR OF APPLE IPHONE 8 - GENIUS BAR WORK AUTHORISATION REPAIR NO. R494016215	NO PHOTO	249.00	-
1	BIKE ACCESSORIES: HELMET	DAMAGED	264.00	264.00
1	BIKE ACCESSORIES: GLOVES	DAMAGED	43.99	43.99
1	BIKE - SHIFTER / HANDLE BAR, BARTAPE, PEDAL, WHEEL SET, LABOUR, DELIVERY - HUP LEONG COMPANY BIKE DAMAGE ASSESSMENT REPORT REFERENCE NO. 83196429-210518	DAMAGED	2,162.00	2,162.00
			3,717.99	3,468.99
	GRAND TOTAL		3,717.99	3,468.99
	RECOMMENDED COST OF REPAIRS			2,750.00

Report Ref No. CS1/LAW21010651/Gtf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.