

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLA639K Toyota Wish

No	Qty	Parts Description	Estimated Parts Price
1	1	Front right door panel ✓	\$ 1,465.20 <i>ht - 1292.30</i>
2	1	Rear bumper assy ✗	\$ 859.20 <i>X</i>
3	1	Rear bumper right retainer ✗	\$ 44.30 <i>X</i>
4	1	Rear bumper right bracket ✗	\$ 43.10 <i>X</i>
5	1	Rear right taillamp ✗	\$ 440.50 <i>X</i>
6	1	Rear right door panel ✓	\$ 1,261.40 <i>ht -</i>
7	1	Rear right door regulator with motor ✓	\$ 493.50 <i>ht - 228.70</i>
8	1	Rear right door weatherstrip ✓	\$ 182.60 <i>cut -</i>
9	1	Rear right door outer handle ✓	\$ 127.20 <i>cut -</i>
10	1	Rear right door lock mechanism ?	\$ 225.80 <i>ht -</i>
11	1	Rear right door checker linkage ?	\$ 121.30 <i>X nn</i>
12	1	Rear right door inner board ?	\$ 478.20 <i>cut -</i>
13	2	Rear right door hinges ?	\$ 120.10 <i>ht -</i>
14	1	Rear right door glass assy ✓	\$ 388.80 <i>bn -</i>
15	1	Rear right door glass outer moulding ✓	\$ 161.40 <i>de - 146.20</i>
16	1	Rear right suspension assy ✗	\$ 860.60 <i>X</i>
17	1	Rear right wheel hub bearing ✗	\$ 272.30 <i>X nn</i>
18	1	Rear axle beam ✗	\$ 1,800.10 <i>X</i>
19	1	Rear right fender ✓	\$ 1,482.30 <i>ht - 977.40</i>
20	1	Rear right fender inner cowling ✗	\$ 128.70 <i>X nn</i>
21	1	Rear right quarter glass moulding ✓	\$ 128.90 <i>X nn -</i>
22	1	Rear windscreen glass moulding ✓	\$ 280.20 <i>X nn</i>
23	1	Rear right 'B' pillar	\$ 1,859.10 <i>RM</i>
			<hr/>
			\$ 13,224.80 <i>5557.60</i>
		less 25%	\$ 3,306.20
			<hr/>
			\$ 9,918.60 <i>4168.20</i>
		<u>Special Nett Items</u>	
1	10	Rear bumper clips	\$ 60.00 <i>30</i>
2	1	Rear no plate with garnish	\$ 100.00 <i>X nn</i>
3	1	Rear right fender sealant	\$ 100.00 <i>40 over</i>
4	1	Rear windscreen glass sealant	\$ 100.00 <i>X</i>
5	1	Rear right wheel rim	\$ 750.00 <i>X</i>
6	1	Rear right tyre	\$ 300.00 <i>X</i>
7	1	Rear right quarter glass sealant	\$ 80.00 <i>40 over</i>
8	1	Rear right side skirting	\$ 1,400.00 <i>cut - 400</i>
9	1	Rear right side skirting sealant	\$ 100.00 <i>X nn</i>
10	10	Rear right side skirting clips	\$ 60.00 <i>20 over</i>
11	6	Rear right fender inner cowling clips	\$ 40.00 <i>X nn</i>
12	8	Rear right door inner board clips	\$ 45.00 <i>20 over</i>
			<hr/>
			\$ 3,135.00 <i>550</i>
		Total parts	<hr/>
			\$ 13,053.60

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SLA639K Toyota Wish

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear right affected area and replace rear right damaged parts.	\$ 1,400.00 900
2	To putty and spray painting rear right portion.	\$ 1,400.00 900
3	To check rear lighting and wiring.	\$ 50.00 X un
4	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 X un
5	To apply anti rust proofing to rear right affected area.	\$ 140.00 40
6	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 X }
7	To remove and install rear right undercarriage parts.	\$ 350.00 X }
8	To balance rear right wheel.	\$ 50.00 X }
9	To conduct wheel alignment.	\$ 120.00 X }
10	To remove and install rear right door lock mechanism.	\$ 80.00 60
11	To check front right and rear right door central locking for function.	\$ 80.00 30
12	To transfer front right door glass to new door.	\$ 80.00 X un
13	To transfer rear right door glass to new door.	\$ 80.00 X un
14	To remove and install rear right door regulator with motor assy.	\$ 80.00 60
15	To remove and install rear right quarter glass.	\$ 80.00 40
16	Towing service.	\$ 100.00 60 ? towing
Total labour :		\$ 4,370.00 un

1220

Total parts : \$ 13,053.60

Total labour : \$ 4,370.00

Total repair cost : \$ 17,423.60

Tanpin 97495749
 18/10/21 @ 350 pm

US Resurvey after repair
 tanpin@lkkauto.com
 07 days

4168.20
 550
 1220
 5938.20
 4584750
 07 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: