Attn:

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd

20 McCallum Street #09-01 Tokio Marine Centre Singapore 069046

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

29 Oct 2021 Date:

Preliminary Advice

Insured Vehicle No : SLU8431J

Ong Chin Kiat

TP Vehicle No : SHD4297T Accident Date : 15/10/2021 Make : HYUNDAI IONIQ HYBRID Assignment Date : 18/10/2021

Date of Inspection : 18/10/2021 Est. Duration of Repair

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

> **59 LOYANG DRIVE** SINGAPORE 508969

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 6,070.28 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 4,142.52 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 4,142.52 |

Lump Sum Repair :S\$

Total Loss Consideration

| New for Old Value | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. K | Cindly |
|---|--|---------------|
| | et us have your authorisation. | |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to consistency check, part prices and labour cost.