

Our Job Ref No : 305489782
Date : 12/10/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508909
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SHC1126D

Fax :

06/10/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: NTUC SJH5508J
2. The finalized amount shall be:
- (a) Spare Parts after List discount _____
- (b) Labour Charges _____
- Total for Part-By-Part Repair Cost** _____
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost \$3,150.00


3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : Thevan
Date : 20/10/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COM OR DELGRO ENGINEERING PTE LTD REPAIR ESTIMATE

Vehicle No.: SHC1126D
Make : TOYOTA
Model : PRIUS
DOA : 7/5/2017

Date : 10/6/2021
Insurance: NTUC
MVA : CHIANG /
Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount	
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70	Def
1	REAR TRUNK LID LOCK			\$457.90	BT
1	REAR TRUNK LID LOGO (PRIUS)			\$52.90	nec
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40	nec
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$60.80	nec
1	REAR BUMPER			\$458.60	Cut
1	REAR BUMPER UNDER COVER			\$552.60	Cut
10	REAR BUMPER CLIP		\$2.20	\$22.00	nec
2	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40	X SUC
2	REAR BUMPER UNDER SIDE COVER LH/RH		\$232.00	\$464.00	DIS
1	REAR BUMPER UNDER COVER CENTRE			\$252.00	X SUC
1	REAR END PANEL			\$602.10	X SUC
1	REAR END PANEL GARNISH			\$165.80	X SUC
1	REAR SMART KEY ANTENNA			\$312.00	X SUC
1	REAR BUMPER TOWING COVER			\$82.70	mis
10	REAR BUMPER CLIPS	x NN	\$2.20	\$22.00	nec
1	REAR BUMPER REINFORCEMENT			\$318.80	BT
	SUB TOTAL			\$4,991.70	
	LESS 25%			\$1,247.93	
	DISCOUNTED TOTAL			\$3,743.78	
1	REAR TRUNK LID APPS STICKER		-10%	\$40.00	nec
1	REAR TRUNK LID COMFORT & TEL NO. STICKER		-10%	\$60.00	nec
1	REAR BUMPER MAT			\$50.00	NETT/nec
1	REAR NUMBER PALTE W/HOLDER		-10%	\$50.00	X SUC
1	REAR BUMPER REVERSE SENSOR		-10%	\$135.70	Cut
	Labour Charge			\$307.13	
	Panel Beating			\$875.00	700
	Spray Painting Charge			\$600.00	500
	Wiring Charge			\$60.00	30
	Tuff Kote			\$60.00	30
	Remove/Refix Reverse Sensor			\$60.00	20
	TOTAL LABOUR			\$1,685.00	
	ESTIMATE TOTAL			\$5,735.91	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.