

REG. BY: Thevan

REF: Ntuc

NS/INC21010659/Vqc

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. MT/1147184-002

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs.

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC1126D

Yr Regn:

7/5, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

toyota prius

c.c 1798

Colour:

blue

A/C: Insured / Std / NI / NA

Sp. Reading

641785

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

STDH83Fu003561361

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

6/10/21

D.O.A.

7/10/21 1630

Survey held at

Comfort

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

no GIA given

20/10/21 Thevan finalised with Mr Chiang LS \$3150, 3 days. (Red \$2585.91, 45%)

Date/Time. File Pass to?

☐

: Prell. Report

11/21/10 Typist

☐

: Final Report

Date/Time. File Return to?

3

Days Of Repair:

3

Resurvey No. of Trlp:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wash and

Survey Fee:

Transportation:

___ S + RS. ___ SI

Prints

Colours

TOTAL

Report Fee:

TP

11/21/10

3150

Date/Time: 07.10.2021 14:22

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4127121

JC NO305489782

STOMER

COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (R) (P) (O)

REGN NO.:

SHC1126D

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)06.10.2021 20:20

DATE/TIME IN

YR OF MANU.

05.07.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU003561361

COMPLETION DATE/TIME:


COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 06.10.2021

NATURE: 3P 06.10.2021

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC1126D

CHIANG

Vehicle No.:

SHC1126D

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COM OR DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC1126D ✓
 Make : TOYOTA
 Model : PRIUS
 DOA : 7/5/2017

Date : 10/6/2021
 Insurance: NTUC
 MVA : CHIANG /
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount	
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			\$889.70	✓ Def
1	REAR TRUNK LID LOCK			\$457.90	✓ BT
1	REAR TRUNK LID LOGO (PRIUS)			\$52.90	✓ nec
1	REAR TRUNK LID LOGO (HYBRID)			\$52.40	✓ nec
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$60.80	✓ nec
1	REAR BUMPER			\$458.60	✓ cut
1	REAR BUMPER UNDER COVER			\$552.60	✓ cut
10	REAR BUMPER CLIP		\$2.20	\$22.00	✓ nec
2	REAR BUMPER SIDE RETAINER LH/RH		\$112.70	\$225.40	✓ SUC
2	REAR BUMPER UNDER SIDE COVER LH/RH		\$232.00	\$464.00	✓ DIS
1	REAR BUMPER UNDER COVER CENTRE			\$252.00	✓ SUC
1	REAR END PANEL			\$602.10	✓
1	REAR END PANEL GARNISH			\$165.80	✓
1	REAR SMART KEY ANTENNA			\$312.00	✓
1	REAR BUMPER TOWING COVER			\$82.70	✓ unis
10	REAR BUMPER CLIPS		\$2.20	\$22.00	✓ nec
1	REAR BUMPER REINFORCEMENT			\$318.80	✓
SUB TOTAL				\$4,991.70	
LESS 25%				\$1,247.93	
DISCOUNTED TOTAL				\$3,743.78	
1	REAR TRUNK LID APPS STICKER			\$40.00	✓ nec
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$60.00	✓ nec
1	REAR BUMPER MAT			\$50.00	✓ NETT/nec
1	REAR NUMBER PLATE W/HOLDER			\$50.00	✓ SUC
1	REAR BUMPER REVERSE SENSOR			\$135.70	✓ Cut
				\$307.13	
Labour Charge					
Panel Beating					
Spray Painting Charge					
Wiring Charge					
Tuff Kote					
Remove/Refix Reverse Sensor					
TOTAL LABOUR				\$1,685.00	
ESTIMATE TOTAL				\$5,735.91	

Theruan@LKKAuto.com
 82235769
 7/10/21 1630
 L/S after repair photo
 3 days wp

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting \$875.00
- To display damaged part(s) during resurvey \$600.00
- Parts prices are subject to confirmation \$60.00
- Third party survey is on a "Without Prejudice Basis" \$900.00
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

700
 500
 20
 30
 20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.