

Our Job Ref No 305489787

Date 11/10/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Luyang Drive, Singapore 508969
Fax: 6548 8156

FINALIZATION FORM


To LKK Fax _____
Attn Mr Thevan
Vehicle Reg No SHA2767H CTPL 08/10/2021


The survey and estimates of the repairs of the above-mentioned vehicle are as follows. -

1. The repair job shall bill to: NTUC --- SJV7177T
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** \$0.00
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$1,750.00

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : MS. LOKE YY
Tel : 62148355
Fax : 65468156

Signature : 
Name : Thevan
Date : 18/10/21

For Official Use Only

| Item | Amount | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|-----------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day | | YES | | |
| 2. Loss of Income Paid | | NO | | |
| 3. Survey Fees | | | | |
| 4. LTA Search Fee | \$7.49 / \$2.00 | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | |
| 6. Overrun | | | | |

Remarks:

REPAIR ESTIMATE

Vehicle No. : SHA2767H

Make : HYUNDAI

Model : IONIQ(G2)

Date: 08/10/21

Insurance: NTUC

MVA: MS. LOKE YY

| Qty | Parts Description / Labour | Type | Unit Price | Amount |
|-----|-----------------------------------|---------|------------|-------------------|
| 1 | REAR BUMPER COVER | | | \$459.40 |
| 10 | REAR BUMPER CLIPS | | | \$22.00 |
| 1 | REAR BUMPER CENTRE MOULDING ASSY | | | \$451.25 |
| 1 | REAR BUMPER REINFORCEMENT | | | \$394.80 |
| 1 | REAR BUMPER LOWER CTR MOULDING | | | \$155.00 |
| 1 | ANTENNA SMARTKEY | | | \$40.50 |
| 1 | REAR BUMPER FOG LAMP | | | \$201.50 |
| 1 | LICENCE LAMP | | | \$85.30 |
| | SUB TOTAL | | | \$1,482.45 |
| | LESS 25% 20% | | | \$370.61 |
| | DISCOUNTED TOTAL | | | \$1,111.84 |
| 1 | REAR NUMBER PLATE WITH TRIM COVER | -10.00% | | \$55.00 |
| 1 | REAR BUMPER REVERSE SENSOR | -10.00% | | \$180.00 |
| | | | | \$235.00 |
| | Labour Charge | | | |
| | PANEL BEATING | | | \$400.00 |
| | SPRAY PAINTING CHARGE | | | \$300.00 |
| | REMOVE/REFIX REVERSE SENSOR | | | \$80.00 |
| | TOTAL LABOUR | | | \$780.00 |
| | ESTIMATE TOTAL | | | \$2,126.84 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan@Lkhauto.com

82235769

8/10/21 1600

L/S after repair photo

2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: