



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000264

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Motor Claim Department

TEL : 63896111

FAX : 62221033

Your Ref. : YN4459P
Vehicle No. : GBE23J
Make & Model : TOYOTA HIACE
Chasis No. : KDH2010146398
Engine No. : 1KD2427931
Accident Date : 06/09/2021
Policy No. : 5069661931-06
Date : 20/10/2021
Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	HEADLIGHT (L/H) <i>Cracked</i>	1.0 PCS	569.23	✓ 569.23
2	WASHER TANK <i>Delc</i>	1.0 PCS	148.02	✓ 148.02
3	WASHER TANK MOTOR <i>new</i>	2.0 PCS	252.20	+ 504.40
4	BONNET <i>Repair</i>	1.0 PCS	667.15	+ 667.15
5	LOGO <i>new</i>	1.0 PCS	83.69	✓ 83.69
6	CORNER PANEL (L/H) <i>Dented</i>	1.0 PCS	292.40	✓ 292.40
7	STEP GARNISH (L/H) <i>new</i>	1.0 PCS	259.35	+ 259.35
8	DC OR (L/H/F)	1.0 PCS	1,824.25	X 1,824.25
9	DOOR HINGE (L/H LOWER)	1.0 PCS	82.30	X 82.30
10	DOOR HINGE (L/H UPPER)	1.0 PCS	82.30	X 82.30
11	FRONT GRILLE TOP GARNISH	1.0 PCS	160.23	X 160.23
12	FRONT GRILLE INNER	1.0 PCS	446.12	X 446.12
13	FRONT GRILLE OUTER (LOWER)	1.0 PCS	292.32	X 292.32
14	FRONT GRILLE CLIP	4.0 PCS	5.00	+ 20.00
15	FRONT BUMPER	1.0 PCS	569.89	+ 569.89
16	BUMPER CLIP	6.0 PCS	6.00	X 36.00
17	FOG LAMP COVER (L/H)	1.0 PCS	68.25	X 68.25
18	BUMPER GRILLE	1.0 PCS	356.25	X 356.25
19	BUMPER SIDE RETAINER (L/H/F)	1.0 PCS	133.20	X 133.20
20	GARNISH (WIRE HARNESS)	1.0 PCS	85.60	X 85.60
21	Discount 25 %			-1,670.24
22	SubTotal (L)			5,010.71
23	DOOR STICKER <i>new</i>	1.0 PCS	25.00	X 25.00
24	SubTotal (S)			25.00
25	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0 X		30 60.00
26	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X		X 120.00
27	TO PROVIDE UNDER TURF COAT	1.0 X		30 150.00



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000264

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attention: Motor Claim Department

TEL : 63896111

FAX : 62221033

Your Ref. : YN4459P

Vehicle No. : GBE23J

Make & Model : TOYOTA HIACE

Chasis No. : KDH2010146398

Engine No. : 1KD2427931

Accident Date : 06/09/2021

Policy No. : 5069661931-06

Date : 20/10/2021

Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
28	PANEL BEAT & REPAIR FRONT DAMAGE	1.0 X		350-750.00
29	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X	660	300-700.00
30	SubTotal			1,780.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 1530
2/5 11.2K
03 Days.

1.2K

SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED FIFTEEN AND CENTS SEVENTY ONE ONLY

E. & O.E

Total	S\$	6,815.71
Discount	S\$	0.00
Net Total	S\$	6,815.71

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.